



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details					
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	M/S Grab Rentals Pte Ltd					
		Document No. 0	3 Media Close #01-03/06 Singapore 138498					
		Document Date 01/02/2023	Work: 65703925					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM8839J	0	19697	66OD/SLM8839J/170123	
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On			
JTDKB3FU203555349	2ZRS034992	6Q	Shashitharan	28/01/2023	8.00	01/02/2023	18.00	
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount		
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: SKW4787K ACC DATE:16/01/23 DRIVE IN:25/01/23 EXCESS: DATE-IN:27/01/23 DATE SURVEY:27/01/23 NO OF REPAIR DAYS:4 BY:taufikh AUTHORIZED ON:270/1/23	*			50.00		
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST	*			198.00		
3	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL	*			1188.00		
4	B	BP-RES2 RESRPAY ACC AFF AREA				1312.00		
5	1	U52116-47050 SUPPORT, FR BUMPER	1.00	95.70		95.70		
6	2	U53802-47100 FENDER SUB-ASSY, FR	1.00	1177.80		1177.80		
7	3	U53876-47110 LINER, FR FENDER, LH	1.00	243.20		243.20		
8	4	U52119-47962 COVER, FR BUMPER	1.00	622.20		622.20		
9	5	U75374-47150 EMBLEM, SIDE PANEL	1.00	65.60		65.60		
For & on behalf of		Customer's Signature	Charge Summary		Total			4,952.50
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle			GST 8.00%			396.20
			Parts					
			Labour					
			Sublet					
			Lubrication/Fluid					
			Others		Less			0.00
					Amount Due			5,348.70

Customer Copy