



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23000827/Uqp3m4 Date: 27/01/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMB 5062Z	Veh. Inspected	SMT 1001G
Policy No.		Coverage (\$)	0.00
Claim No.	D23000282MFBP	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	26/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA ALPHARD (A)	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	AGH300361705	Colour	BROWN
Odometer	29685 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/65 R16	GOODYEAR	7 mm
L/H Front Tyre	215/65 R16	GOODYEAR	7 mm
R/H Rear Tyre	215/65 R16	GOODYEAR	7 mm
L/H Rear Tyre	215/65 R16	GOODYEAR	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	18/01/2023	Inspection Date	31/01/2023
Survey held at	1 KAKI BUKIT AVE 6 #01-73 AUTOBAY@KAKI BUKIT		
Repairer	SPEEDWERKZ PTE LTD		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	