

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0023/2023
DATE : 27-JAN-2023

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD #02-01
UOI BUILDING
S(068909)
TEL : 62227733/64909318
FAX : 63273869 / 72
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAY YANLING, DORA (ZHENG YANLING, DORA)
ADDRESS : BLK 202 BUKIT BATOK STREET 21
#12-100
S(650202)
TELEPHONE NO : 97461839

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DH0M110162371804
VEHICLE NO : SGL512T
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2294428A
CHASSIS NO : SJNFEAJ11U1694378
MILEAGE : 1 KM
DATE IN : 27/01/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 21/01/2023

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 FRT LICENCE PLATE <i>OK</i>	FLP			60.00
2 BUMPER SET FR <i>OK</i>	62022-4EA0H	811.30		
3 GROMMET(\$2.6X2) <i>OK</i>	01281-00111			5.20
4 ENERGY ABSORBER ?	62090-4EA1B	260.40		
5 ARMATURE ASSY-F ?	F2030-4ENMA	898.70		
6 COVER-BUMPER ?	622A0-4EA0A	24.90		
7 GRILLE-RADIATOR ?	62310-4EA1A	624.50		
8 EMBLEM RAD GRIL ?	62890-4EA0A	86.20		
9 LAMP ASSY-RH <i>OK</i>	26010-4EA2A	660.10		
10 CLIP(\$1.4X10) <i>OK</i>	01553-05933	14.00		
11 SUNDRIES <i>OK</i>	NPN			30.00
SUB TOTAL		3380.10	0.00	95.20
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		676.02	0.00	0.00
GRAND TOTAL		2704.08	0.00	95.20
OVERALL TOTAL		2799.28		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
2	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
4	ZZ/001	REPAIR RH FR FENDER & HOOD RENEW FR BUMPER	840.00	560
5	ZZ/002	S/PAINT FR BUMPER, RH FR FENDER & HOOD	800.00	750
TOTAL LABOUR CHARGES			1808.00	

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGL512T

TOTAL LABOUR CHARGES	1808.00
TOTAL SPARE PARTS CHARGES	2799.28
GRAND TOTAL	4607.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME : *Pawan - HP 9000068*
SURVEYED DATE : *30/01/23 @ 1010*
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00 *4 days*
LIABILITY : 0.00 *7/P*
REMARKS : *EXCESS: TBA*
Revers
Resny before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: