

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓
2 NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
4 ZZ/001	REPAIR RH FR FENDER & HOOD RENEW FR BUMPER	840.00 560	✓
5 ZZ/002	S/PAINT FR BUMPER, RH FR FENDER & HOOD	800.00 750	1000 ✓
	TOTAL LABOUR CHARGES	1808.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 FRT LICENCE PLATE <i>de</i> ✓	FLP			60.00	✓
2 BUMPER SET FR <i>de</i> ✓	62022-4EA0H	811.30	✓		
3 GROMMET(\$2.6X2) <i>de</i> ✓	01281-00111			5.20	✓
4 ENERGY ABSORBER <i>?</i> ✓	62090-4EA1B	260.40	✓		
5 ARMATURE ASSY-F <i>?</i> x <i>kan</i>	F2030-4ENMA	898.70	x		
6 COVER-BUMPER <i>?</i> x <i>kan</i>	622A0-4EA0A	24.90	x		
7 GRILLE-RADIATOR <i>?</i> ✓ <i>OK</i> ✓	62310-4EA1A	624.50	✓		
8 EMBLEM RAD GRIL <i>?</i> ✓ <i>de</i> ✓	62890-4EA0A	86.20	✓		
9 LAMP ASSY-RH <i>OK</i> ✓	26010-4EA2A	660.10	✓		
10 CLIP(\$1.4X10) <i>de</i> ✓	01553-05933	14.00	✓		
11 SUNDRIES <i>de</i>	NPN			30.00	20 ✓
SUB TOTAL		3380.10		0.00	95.20
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		676.02		0.00	0.00
GRAND TOTAL		2704.08		0.00	95.20
OVERALL TOTAL		2799.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGL512T

TOTAL LABOUR CHARGES	1808.00
TOTAL SPARE PARTS CHARGES	2799.28
GRAND TOTAL	4607.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME : *Patim - HP 9000068*
SURVEYED DATE : *30/01/23 @ 1010*
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00 *4 days*
LIABILITY : 0.00 *7/P*
REMARKS : *EXCESS: T89*

*Repair
Resurvey before print*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0023/2023
DATE : 27-JAN-2023

OD => Rasu (LKK-Auto)

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD #02-01
UOI BUILDING
S(068909)
TEL : 62227733/64909318
FAX : 63273869 / 72
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAY YANLING, DORA (ZHENG YANLING, DORA)
ADDRESS : BLK 202 BUKIT BATOK STREET 21
#12-100
S(650202)
TELEPHONE NO : 97461839

ZHR

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DHOM110162371804
VEHICLE NO : SGL512T
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2294428A
CHASSIS NO : SJNFEAJ11U1694378
MILEAGE : 1 KM
DATE IN : 27/01/2023
LIABILITY : 0.00
EXCESS CLAUSE : 500.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 21/01/2023

Recommend Repair 4 Days.

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
2	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
4	ZZ/001	REPAIR RH FR FENDER & HOOD RENEW FR BUMPER	840.00	560.00
5	ZZ/002	S/PAINT FR BUMPER, RH FR FENDER & HOOD LH FR FENDER(SUPPLE)	800.00	1000.00
6	ZZ/003	RECONDITION AIRCOND & REFILL GAS - SUPPLE <i>A new</i>	240.00	240.00
TOTAL LABOUR CHARGES			2048.00	1968.00

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1 CONDENSER ASSY-SUPPLE	✓ <i>bt</i>	92110-00Q0E			751.10	OK ✓ A
2 LH HEADLAMP-SUPPLE	✓ <i>cm</i>	26060-4EA2A	660.10			OK ✓ A
3 FENDER,ARC-SUPPLE	✓ <i>cm</i>	63810-4EA0A	584.20			OK ✓ A
4 SUNDRIES		NPN			20.00	OK
5 FRT LICENCE PLATE		FLP			60.00	OK
6 BUMPER SET FR		62022-4EA0H	811.30			OK
7 GROMMET(\$2.6X2)		01281-00111			5.20	OK
8 ENERGY ABSORBER		62090-4EA1B	260.40			OK
9 ARMATURE ASSY-F		F2030-4ENMA	898.70			X
10 COVER-BUMPER		622A0-4EA0A	24.90			X
11 GRILLE-RADIATOR		62310-4EA1A	624.50			OK
12 EMBLEM RAD GRIL		62890-4EA0A	86.20			OK
13 LAMP ASSY-RH		26010-4EA2A	660.10			OK
14 CLIP(\$1.4X10)		01553-05933	14.00			OK
SUB TOTAL			3700.80	0.00	836.30	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			740.16	0.00	0.00	
GRAND TOTAL			2960.64	0.00	836.30	
OVERALL TOTAL			3796.94			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGL512T

NETT ITEM	3700.80
LESS 20.00%)	-740.16
NETT AMOUNT	2960.64
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	836.30
LESS .00%)	0.00
SPECIAL NETT AMOUNT	836.30
TOTAL LABOUR CHARGES	1968.00
TOTAL SPARE PARTS CHARGES	3796.94
TOTAL CHARGES	5764.94
LESS EXCESS	500.00
TOTAL	5264.94
ADD 8 % GST	421.20
GRAND TOTAL	5686.14