

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0023/2023
DATE : 27-JAN-2023

OD => Rasul (LKK-Auto)

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD #02-01
UOI BUILDING
S(068909)
TEL : 62227733/64909318
FAX : 63273869 / 72
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAY YANLING, DORA (ZHENG YANLING, DORA)
ADDRESS : BLK 202 BUKIT BATOK STREET 21
#12-100
S(650202)
TELEPHONE NO : 97461839

ZHR

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DH0M110162371804
VEHICLE NO : SGL512T
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2294428A
CHASSIS NO : SJNFEAJ11U1694378
MILEAGE : 1 KM
DATE IN : 27/01/2023
LIABILITY : 0.00
EXCESS CLAUSE : 500.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 21/01/2023

Recommend Repair 4 Days.

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
2	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
4	ZZ/001	REPAIR RH FR FENDER & HOOD RENEW FR BUMPER	840.00	560.00
5	ZZ/002	S/PAINT FR BUMPER, RH FR FENDER & HOOD LH FR FENDER(SUPPLE)	800.00	1000.00
6	ZZ/003	RECONDITION AIRCOND & REFILL GAS - SUPPLE	240.00	240.00
TOTAL LABOUR CHARGES			2048.00	1968.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	CONDENSER ASSY-SUPPLE	92110-00Q0E			751.10	OK
2	LH HEADLAMP-SUPPLE	26060-4EA2A	660.10			OK
3	FENDER,ARC-SUPPLE	63810-4EA0A	584.20			OK
4	SUNDRIES	NPN			20.00	OK
5	FRT LICENCE PLATE	FLP			60.00	OK
6	BUMPER SET FR	62022-4EA0H	811.30			OK
7	GROMMET(\$2.6X2)	01281-00111			5.20	OK
8	ENERGY ABSORBER	62090-4EA1B	260.40			OK
9	ARMATURE ASSY-F	F2030-4ENMA	898.70			X
10	COVER-BUMPER	622A0-4EA0A	24.90			X
11	GRILLE-RADIATOR	62310-4EA1A	624.50			OK
12	EMBLEM RAD GRIL	62890-4EA0A	86.20			OK
13	LAMP ASSY-RH	26010-4EA2A	660.10			OK
14	CLIP(\$1.4X10)	01553-05933	14.00			OK
SUB TOTAL			3700.80	0.00	836.30	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			740.16	0.00	0.00	
GRAND TOTAL			2960.64	0.00	836.30	
OVERALL TOTAL			3796.94			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGL512T

NETT ITEM	3700.80
LESS 20.00%)	-740.16
NETT AMOUNT	2960.64
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	836.30
LESS .00%)	0.00
SPECIAL NETT AMOUNT	836.30
TOTAL LABOUR CHARGES	1968.00
TOTAL SPARE PARTS CHARGES	3796.94
TOTAL CHARGES	5764.94
LESS EXCESS	500.00
TOTAL	5264.94
ADD 8 % GST	421.20
GRAND TOTAL	5686.14
