

7-Feb-2023

INS/IC/ZHR/0023/2023

UNITED OVERSEAS INSURANCE LTD
146 Robinson Road
#02-01 UOI Building
S(068909)

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SGL512T
POLCY NO. : DH0M110162371804

Further to our claim INS/IC/ZHR/0023/202 we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

<u>Replacement of Damaged Items</u>		
1	CONDENSOR <i>bt ✓</i>	\$751.10 S/NETT
2	LH HEADLAMP <i>ca ✓</i>	\$660.10 NETT
3	FENDER-ARC <i>ca ✓</i>	\$584.20 NETT
<u>Labour</u>		
1	RECONDITION AIRCOND & REFILL GAS	\$240.00 ✓
2	REPAIR LH FR FENDER	\$195.00 X
3	S/PAINT LH FR FENDER	\$250.00 ✓
TOTAL		\$2,680.40

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully
TAN CHONG MOTOR SALES PTE LTD

[Signature]
M.Z. HRI
Insurance Claim Dept

Cc: Surveyor

[Signature]
Rasul
08/02/23

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0023/2023
DATE : 27-JAN-2023

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD #02-01
UOI BUILDING
S(068909)
TEL : 62227733/64909318
FAX : 63273869 / 72
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAY YANLING, DORA (ZHENG YANLING, DORA)
ADDRESS : BLK 202 BUKIT BATOK STREET 21
#12-100
S(650202)
TELEPHONE NO : 97461839

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DH0M110162371804
VEHICLE NO : SGL512T
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2294428A
CHASSIS NO : SJNFEAJ11U1694378
MILEAGE : 1 KM
DATE IN : 27/01/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 21/01/2023

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
2	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
4	ZZ/001	REPAIR RH FR FENDER & HOOD RENEW FR BUMPER	840.00	560
5	ZZ/002	S/PAINT FR BUMPER, RH FR FENDER & HOOD	800.00	750
TOTAL LABOUR CHARGES			1808.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 FRT LICENCE PLATE <i>OK</i>	FLP			60.00
2 BUMPER SET FR <i>OK</i>	62022-4EA0H	811.30		
3 GROMMET(\$2.6X2) <i>OK</i>	01281-00111			5.20
4 ENERGY ABSORBER <i>? OK</i>	62090-4EA1B	260.40		
5 ARMATURE ASSY-F <i>?</i>	F2030-4ENMA	898.70		
6 COVER-BUMPER <i>?</i>	622A0-4EA0A	24.90		
7 GRILLE-RADIATOR <i>? OK</i>	62310-4EA1A	624.50		
8 EMBLEM RAD GRIL <i>? OK</i>	62890-4EA0A	86.20		
9 LAMP ASSY-RH <i>OK</i>	26010-4EA2A	660.10		
10 CLIP(\$1.4X10) <i>OK</i>	01553-05933	14.00		
11 SUNDRIES <i>OK</i>	NPN			30.00
SUB TOTAL		3380.10	0.00	95.20
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		676.02	0.00	0.00
GRAND TOTAL		2704.08	0.00	95.20
OVERALL TOTAL		2799.28		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGL512T

TOTAL LABOUR CHARGES 1808.00
TOTAL SPARE PARTS CHARGES 2799.28

GRAND TOTAL 4607.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME
SURVEYED DATE
AUTHORIZED DATE
EXCESS CLAUSE
LIABILITY
REMARKS

: *Plasma - 4p 900cc/68*
: *30/01/23 @ 1010*
:
: *4 days*
: *0.00*
: *0.00*
: *7/P*

EXCESS: TBA

*Repair
Resin before paint*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.