





# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Income Insurance Limited

Accident Date : 17.01.2023

Not Notarised  
11 Reg &  
Permy Atk Paing  
4 days

Policy No: Third Party

Date: 27.01.2023

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

| 数量<br>Quantity | 货名<br>DESCRIPTION                                                                                                                                            | 单价<br>Unit Price | 银 Amount 额<br>\$ cts. |
|----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-----------------------|
|                | Estimate Cost Of Repair To "Honda Vezel" Reg. No. SLN7434U<br>Claiming Against Your Insured Reg. No. SJX3827S                                                |                  |                       |
| 1pc            | Front Bumper                                                                                                                                                 |                  | 709.00 ✓              |
| 12pcs          | Front Bumper Clips                                                                                                                                           | 3.80             | 45.60 ✓               |
| 1pc            | Front Bumper Corner Retainer RH                                                                                                                              |                  | 46.00 ✓               |
| 1pc            | Front Bumper Lower Lip                                                                                                                                       |                  | 442.00 X              |
| 1pc            | Headlamp RH (LED) (Top Holder Broken)                                                                                                                        |                  | 2,045.00 ✓            |
| 1pc            | Front Fender RH                                                                                                                                              |                  | 687.00 ✓              |
| 1pc            | Front Fender Arch Protector                                                                                                                                  |                  | 198.00 ✓              |
| 20pcs          | Front Fender Arch Protector Clips LH / RH                                                                                                                    | 3.80             | 76.00 ✓               |
| 1pc            | Front Fender Badge (Hybrid)                                                                                                                                  |                  | 75.00 ✓               |
|                | Less 20%                                                                                                                                                     |                  | 4,323.60              |
|                |                                                                                                                                                              |                  | 864.72                |
|                |                                                                                                                                                              |                  | 3,458.88              |
|                | To Conduct Electrical Check, Focus Headlamp                                                                                                                  |                  | 30.00 200             |
|                | To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray<br>/ Replaced / Repair Panel                                                               |                  | 50.00 300             |
|                | Labour Charge - Panel Beating, Repairing of Front RH Door, Door<br>Pillar, Rocker Panel, Rear Fender Arch Panel, Transfer Door<br>Fitting & Part Replacement |                  | 600.00 400            |
|                | To Respray Affected Areas (2K- 2 Tone)                                                                                                                       |                  | 850.00 500            |
|                | To Reseal Paint Protection (Diamondbrite Ceramic) to Spray Paint Areas                                                                                       |                  | 450.00 X              |
|                | Total :                                                                                                                                                      |                  | 5,438.88              |

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: