

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000832/KVP3Q2
Date: 05/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00238342204	
Claimant Vehicle No :	SLU6830D	Insured Vehicle No :	SJB2121S	
Date of Loss:	23/01/2023	Nature of Claim:	TP	Claim No: SNM23D200577/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU6830D		Engine No:	27492030832653
Make & Model:	MERCEDES-BENZ E200, 2.0 SEDAN EXCLUSIVE (A)		Chassis No:	WDD2130422A113718
Reg. Date:	11/12/2017 (Man. Year: 2016)		Odometer:	80494 km
Colour:	Metallic Grey			
Engine Capacity:	1991 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Toyo 8 mm	Rear Left Side:	Pirelli 3 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Pirelli 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,908.80	11,236.50	-1,327.70	-13.40
Miscellaneous Items	220.00	570.00	-350.00	-159.09
Labour	428.40	470.40	-42.00	-9.80
Paintwork Labour	627.78	627.78	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,184.98	12,904.68	-1,719.70	-15.38
+ GST 8.00/8.00% (S\$)	894.80	1,032.37	-137.57	-15.37
Nett Amount (S\$)	12,079.78	13,937.05	-1,857.27	-15.38

INSPECTION

Date of Assignment:	27/01/2023	Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	30/01/2023	Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts: 143	MERCEDES-BENZ E200 2.0 SEDAN EXCLUSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU6830D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*Spare Parts		9,008.00 F	*10,215.00 F	
					Sub Total (\$)	9,008.00	10,215.00
					+ Margin on L,N Items 10.00/10.00% (\$)	900.80	1,021.50
					Total Parts (\$)	9,908.80	11,236.50

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Extra	220.00	570.00
			Sub Total (\$\$)	570.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Including Material	New	627.78	627.78
Labour Items				
2	Total of Labour	New	428.40	470.40
			Gross Labour Cost (\$\$)	1,098.18

Report was unsubmitted during this print-out.

< END OF ESTIMATES >