



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No. 203165/000

LKK

DATE: 03/02/2023

OUR REF: UAPL1575

REPAIR ESTIMATE YOU THE HONDA FREED NO: SKC6716H

- 1 REAR TAILGATE ASSY *Devised*
- 2 REAR TAILGATE HINGES *Here*
- 2 REAR TAILGATE DAMPERS *Here*
- 1 REAR TAILGATE INNER TRIM BOARD *cracked*
- 1 REAR TAILGATE INNER LOCK *Here*
- 1 REAR TAILGATE STRIKER *Here*
- 1 REAR TAILGATE LOGO *Here*
- 1 REAR TAILGATE INNER PULL POCKET *Here*
- 1 REAR TAILGATE WEATHERSTRIP *Here*
- 1 REAR TAILGATE OPENING SWITCH SET *cracked*
- 2 REAR TAILLAMP ASSY *ut*
- 1 REAR END PANEL *Devised*
- 1 REAR END PANEL INNER GARNISH *Devised*
- 1 REAR KEYLESS SENSOR *Here*
- 1 REAR WINDSCREEN GLASS MOULDING *Here*
- 1 REAR BUMPER ASSY *Devised*
- 2 REAR BUMPER BRACKET *Here*
- 2 REAR BUMPER SIDE RETAINERS *Here*
- 1 REAR FLOOR PANEL
- 1 REAR FLOOR BOARD COVER *Here*

4817.20

3853.76

LESS 20%.....

SPECIAL NETT:-

- 1 REAR WINDSCREEN DAM RUBBER *Here*
- 1 REAR NUMBER PLATE *Here*
- 1 REAR REVERSE SENSOR *Here*

260

LABOUR CHARGES:-

- TO DISM/REWIRE REAR DAMAGED PORTION
- TO DISM/RENEW REAR REVERSE SENSOR
- TO PANEL BEAT DAMAGED PORTION
- TO PUTTY AND RESPRAY DAMAGED PORTION
- TO SPRAY UNDERCOATING IN REPAIR
- TO DISM/REFIX REAR WINDSCREEN IN REPAIR
- TO DISM/REFIX REAR SEAT, TRAY ASSY, PILLER LINING, ROOF LINING

1920

GB31036532

TP Somp

Xiao Chen

\$	1,385.60	1288
\$	83.80 X	
\$	331.80 X	
\$	313.40	
\$	269.50	
\$	32.00 X	
\$	42.00	
\$	48.50 X	
\$	227.90 X	
\$	197.40	
\$	1,037.20	760
\$	685.00	
\$	180.80	
\$	189.50 X	
\$	112.80	
\$	968.30	
\$	97.00 X	
\$	140.80 X	
\$	1,145.70 X	
\$	187.60 X	
\$	7,676.60	
\$	1,535.32	
\$	6,141.28	

\$	60.00	
\$	45.00 X	
\$	280.00	200

\$	200.00	30
\$	100.00	50
\$	1,200.00	800
\$	1,200.00	800
\$	200.00	60
\$	160.00	120
\$	220.00	60
\$	9,806.28	

total: 6033.76

4/51 4.8K

06 Days

4.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: