

ASS REC. BY:

REF:

CS/EG123000834/Dnp³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: 700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 130K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 71P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHE 9552Y Yr Regn: Sept / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier c.c. 1998

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 48669 T/Radio: Insured / Std / NI / NA

Eng/No: BARZ165536

C/No: JTBZB3G450J004887

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55 R18

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Michelin

Front Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 24/01/2023 D.O.I. 30/01/2023

Survey held at Vin's Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Brgo OD
	MV 130K
	LTA 50.3K
	HL 71.7K
06/03/23	COR 71P 18,224.00 with 5 days of 1yr (Red, #2626, 13%)

Date/Time, File Pass to?

1) 30/3/23

Date/Time, File Return to?

2)

☐: Preli. Report☐: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 3

Report Format: OD

Lump Sum / I.B.I.: (\$ 18224)

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)☐: Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	738I
Vehicle Details	
Vehicle No.:	SNE9552Y
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jan 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER M GRADE
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	8ARZ165536
Chassis No.:	JTEZB3GH50J004887
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$30,806.00
Original Registration Date:	30 Sep 2019
First Registration Date:	30 Sep 2019
Transfer Count:	1
Actual ARF Paid:	\$35,129.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2029
PARF Rebate Amount:	\$26,346.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$37,912.00
COE Rebate Amount:	\$24,000.00
Total Rebate Amount:	\$50,346.00

The information contained herein is correct as at 26 Jan 2023

OK

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Ergo Insurance Pte Ltd
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 5
SINGAPORE 038985

Claim Details

Case Ref. No. : OD/012023/5940
Date : 26-01-2023
Accident Date : 24-01-2023

Vehicle Details

Make & Model : Toyota HARRIER M GRADE
Chassis No : JTEZB3GH50J004887
Registration No : SNE9552Y

S/N	Description	Qty	Amount (\$\$)	
1	RH HEADLAMP <i>money broken</i>	1.00	\$3,500.00	✓
2	LH HEADLAMP <i>money broken</i>	1.00	\$3,500.00	✓
3	RH HEADLAMP SPONGE (WHITE) <i>& crack</i>	1.00	\$40.00	✓
4	LH HEADLAMP SPONGE (WHITE) <i>HH</i>	1.00	\$40.00	X
5	RH HEADLAMP LOWER BRACKET <i>& 1st</i>	1.00	\$50.00	✓
6	LH HEADLAMP LOWER BRACKET <i>HH</i>	1.00	\$50.00	X
7	FRONT GRILLE <i>& crack</i>	1.00	\$650.00	✓
8	FRONT GRILLE RH BRACKET <i>& broken</i>	1.00	\$60.00	✓
9	FRONT GRILLE LH BRACKET <i>& broken</i>	1.00	\$60.00	✓
10	FRONT GRILLE EMBLEM <i>& crack / money broken</i>	1.00	\$570.00	✓
11	FRONT RADAR WITH BRACKET <i>& broken / money broken</i>	1.00	\$920.00	✓
12	FRONT BUMPER <i>torn / crack</i>	1.00	\$1,300.00	✓
13	FRONT BUMPER CENTER LOWER GRILLE <i>cut</i>	1.00	\$210.00	✓
14	FRONT BUMPER CENTER LOWER GARNISH <i>HH</i>	1.00	\$250.00	X
15	FRONT BUMPER RH FOG LAMP <i>HH</i>	1.00	\$170.00	X
16	FRONT BUMPER LH FOG LAMP <i>HH</i>	1.00	\$170.00	X
17	FRONT BUMPER RH FOG LAMP BRACKET <i>HH</i>	1.00	\$90.00	X
18	FRONT BUMPER LH FOG LAMP BRACKET <i>HH</i>	1.00	\$90.00	X
19	FRONT BUMPER LOWER PAD <i>HH</i>	1.00	\$220.00	X
20	FRONT BUMPER RH SIDE RETAINER <i>HH</i>	1.00	\$60.00	X
21	FRONT BUMPER LH SIDE RETAINER <i>HH</i>	1.00	\$60.00	X
22	FRONT BUMPER TOP BEAM <i>& 1st</i>	1.00	\$160.00	✓
23	FRONT BUMPER SPONGE <i>& torn</i>	1.00	\$70.00	✓
24	FRONT BUMPER REINFORCEMENT <i>& 2nd</i>	1.00	\$280.00	✓
25	FRONT BUMPER CLIPS <i>HH</i>	10.00	\$20.00	✓
26	FRONT RH FENDER <i>2nd</i>	1.00	\$480.00	✓
27	FRONT RH FENDER INNER SHIELD <i>HH</i>	1.00	\$240.00	X
28	FRONT RH FENDER INNER SHIELD CLIPS <i>HH</i>	10.00	\$20.00	X

11870.00

13,057.00

Margin: 10%

\$13,330.00

\$1,333.00

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

29	FRONT NO.PLATE HU	SH 280.00 =	1.00	\$14,663.00
30	FRONT BUMPER PARKING SENSOR ? Down	Labour 1500.00	1.00	\$40.00 X
31	TO RESET HEADLAMP SYSTEM		1.00	\$280.00 2 ✓
32	TO RESET RADAR SYSTEM		1.00	\$280.00 } 300/-
33	TO REPAIR DAMAGES		1.00	\$280.00 } 150/-
34	TO SPRAY PAINTING		1.00	\$800.00 600/-
				\$980.00 600/-
Subtotal w/o GST:				\$17,403.00

30/01/2023 @ 1600hrs


Not Actual

Excess TSA- 5 days.

P/Pat. Photo after sign
with changed parts.



LKK Auto



- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Issued by Iswan

This is a computer-generated document. No signature is required.



AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

(SUPPLEMENTARY)

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/012023/5940
Policy No:	DMPG22013468	Date of Loss:	24/01/2023
Vehicle Reg. No.:	SNE9552Y	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAY JUNJIE		
Make/Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Vehicle Reg. Date:	30/09/2019
Vehicle Colour:	BLACK	Chassis No:	JTEZB3GH50J004887
Engine No:	8ARZ165536		
Odometer:	48669 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	3,267.00
Miscellaneous Items	0.00
Labour	180.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	3,447.00
+ GST 8.00% (\$\$)	275.76
Nett Amount (\$\$)	3,722.76
+ Previous Estimates (\$\$)	18,795.24
Claim Total (\$\$)	22,518.00

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Feb 2023)
Parts: M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Vin's Motor Pte Ltd/SNE9552Y/01/02/2023 14:36
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.


Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET CHROME MOULDING <i>monty broken</i>	0.00	0.00	*250.00 F ✓
2	1		*BONNET LOCK <i>1st</i>	0.00	0.00	*70.00 F ✓
3	1		*FRONT SUPPORT PANEL <i>2nd</i>	0.00	0.00	*650.00 F ✓
4	1		*BRACE PANEL <i>1st</i>	0.00	0.00	*280.00 F ✓
5	1		*AIRCON CONDENSER <i>1st</i>	0.00	0.00	*1,100.00 F ✓
6	1		*INTER COOLER <i>1st</i>	0.00	0.00	*420.00 F ✓
7	1		*RADIATOR TOP RH SIDE GUIDE <i>defunct</i>	0.00	0.00	*50.00 F ✓
8	1		*RADIATOR TOP LH SIDE GUIDE <i>defunct</i>	0.00	0.00	*50.00 F ✓
9	1		*RADIATOR LOWER RH SIDE GUIDE <i>defunct</i>	0.00	0.00	*50.00 F ✓
10	1		*RADIATOR LOWER LH SIDE GUIDE <i>defunct</i>	0.00	0.00	*50.00 F ✓

F=Franchise part.


Sub Total (\$\$) 2,970.00
+ Margin on L,N Items 10.00% (\$\$) 297.00
Total Parts (\$\$) 3,267.00

Vin's Motor Pte Ltd/SNE9552Y/01/02/2023 14:36. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS



2kk And





LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REFILL AIRCON GAS	New	180.00 120/-
Gross Labour Cost (\$\$)			180.00

Vin's Motor Pte Ltd/SNE9552Y/01/02/2023 14:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >