

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Ergo Insurance Pte Ltd
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 5
SINGAPORE 038985

Claim Details

Case Ref. No. : OD/012023/5940
Date : 26-01-2023
Accident Date : 24-01-2023

Vehicle Details

Make & Model : Toyota HARRIER M GRADE
Chassis No : JTEZB3GH50J004887
Registration No : SNE9552Y

S/N	Description	Qty	Amount (\$)	
1	RH HEADLAMP <i>money broken</i>	1.00	\$3,500.00	✓
2	LH HEADLAMP <i>money broken</i>	1.00	\$3,500.00	✓
3	RH HEADLAMP SPONGE (WHITE) <i>2 crack</i>	1.00	\$40.00	✓
4	LH HEADLAMP SPONGE (WHITE) <i>44</i>	1.00	\$40.00	X
5	RH HEADLAMP LOWER BRACKET ?	1.00	\$50.00	?
6	LH HEADLAMP LOWER BRACKET <i>44</i>	1.00	\$50.00	X
7	FRONT GRILLE <i>2 crack</i>	1.00	\$650.00	✓
8	FRONT GRILLE RH BRACKET ?	1.00	\$60.00	?
9	FRONT GRILLE LH BRACKET ?	1.00	\$60.00	?
10	FRONT GRILLE EMBLEM <i>2 crack</i>	1.00	\$570.00	✓
11	FRONT RADAR WITH BRACKET ?	1.00	\$920.00	?
12	FRONT BUMPER <i>torn / crack</i>	1.00	\$1,300.00	✓
13	FRONT BUMPER CENTER LOWER GRILLE <i>cut</i>	1.00	\$210.00	✓
14	FRONT BUMPER CENTER LOWER GARNISH <i>44</i>	1.00	\$250.00	X
15	FRONT BUMPER RH FOG LAMP <i>44</i>	1.00	\$170.00	X
16	FRONT BUMPER LH FOG LAMP <i>44</i>	1.00	\$170.00	X
17	FRONT BUMPER RH FOG LAMP BRACKET <i>44</i>	1.00	\$90.00	X
18	FRONT BUMPER LH FOG LAMP BRACKET <i>44</i>	1.00	\$90.00	X
19	FRONT BUMPER LOWER PAD <i>44</i>	1.00	\$220.00	X
20	FRONT BUMPER RH SIDE RETAINER <i>44</i>	1.00	\$60.00	X
21	FRONT BUMPER LH SIDE RETAINER <i>44</i>	1.00	\$60.00	X
22	FRONT BUMPER TOP BEAM ?	1.00	\$160.00	?
23	FRONT BUMPER SPONGE ?	1.00	\$70.00	?
24	FRONT BUMPER REINFORCEMENT ?	1.00	\$280.00	?
25	FRONT BUMPER CLIPS <i>44</i>	10.00	\$20.00	✓
26	FRONT RH FENDER <i>2 crack</i>	1.00	\$480.00	✓
27	FRONT RH FENDER INNER SHIELD <i>44</i>	1.00	\$240.00	X
28	FRONT RH FENDER INNER SHIELD CLIPS <i>44</i>	10.00	\$20.00	X

\$13,330.00

Margin: 10%

\$1,333.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G


			\$14,663.00	
29	FRONT NO.PLATE HU	1.00	\$40.00	X
30	FRONT BUMPER PARKING SENSOR ?	1.00	\$280.00	?
31	TO RESET HEADLAMP SYSTEM	1.00	\$280.00	300/-
32	TO RESET RADAR SYSTEM	1.00	\$280.00	150/-
33	TO REPAIR DAMAGES	1.00	\$880.00	600/-
34	TO SPRAY PAINTING	1.00	\$980.00	600/-
Subtotal w/o GST:			\$17,403.00	

30/01/2023 @ 1600hrs

Not Actual

Excess TBA- 5 days.

P/Pat. Photo after sign
with changed parts.



LKK Auto



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Iswan

This is a computer-generated document. No signature is required.