



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY		Ref: CC4/ASM23000850/Upa3q2 Date: 09/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7794D	Veh. Inspected	SLC 4432C
Policy No.	P2478218	Coverage (\$)	0.00
Claim No.	S3M04ICE	Excess (\$)	0.00
Assign From		Assign Date	26/01/2023
2. Vehicle Particulars & Condition			
Make & Model	SSANGYONG TIVOLI (A)	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KPT30B1USGP077677	Colour	RED
Odometer	89738 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45Z R18	FALKEN	7 mm
L/H Front Tyre	225/45Z R18	FALKEN	7 mm
R/H Rear Tyre	225/45Z R18	FALKEN	7 mm
L/H Rear Tyre	225/45Z R18	FALKEN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/01/2023	Inspection Date	26/01/2023
Survey held at	1 Kaki Bukit Avenue 6 #01-73 Autobay S417883		
Repairer	SPEEDWERKZ PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	