Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH 31 Jan 2023 Date:

Preliminary Advice

Vehicle No : SGU9933E Accident Date : 24/12/2022 Policy No. Make : MERCEDES-BENZ A180 R17 : SP2003021716-01

Assignment Date : 28/01/2023 **Excess** : S\$600.00

Date of Inspection : 24/12/2023 (Desktop Survey)

Inspection At : VIN'S MOTOR PTE LTD Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,604.00
Revised Amount	:S\$	1,731.00
Check Items (Estimated)	:S\$	253.00
Total	:S\$	1,984.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	27,071.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,929.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
	us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Part by Part repair. According to the repairer, there are no second-hand parts available. Surveyor physically checked the vehicle and re-adjusted the Repair Cost. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.