



AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD/012023/5939
Policy No:	SP2003021716-01	Date of Loss:	24/12/2022
Vehicle Reg. No.:	SGU9933E	Driveable?	
Driver Age/Info:	44 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM CHIEN WEI, CHRISTOPHER	Contact No:	+6591809933
Driver:	SIM CHIEN WEI, CHRISTOPHER		
Make/Model:	MERCEDES-BENZ A180 R17, 1.6 (A)	Vehicle Reg. Date:	28/10/2015
Vehicle Colour:	Purple		
Engine No:	27091030793495	Chassis No:	WDD1760422J409335
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO POLICE		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	1,164.00
Miscellaneous Items	0.00
Labour	940.00
Paintwork Labour	500.00
Towing	0.00
Gross Total (\$\$)	2,604.00
+ GST 8.00% (\$\$)	208.32
Nett Amount (\$\$)	2,812.32

This claim is handled by: MUHAMMAD ISWAN BIN ISHAK

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jan 2023)
Parts: 144 MERCEDES-BENZ A180 R17 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Vin's Motor Pte Ltd/SGU9933E/27/01/2023 16:36
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front windscreen glass <i>Crack</i>	0.00	0.00	*550.00 F ✓
2	1		*Rain sensor <i>Hec</i>	0.00	0.00	*200.00 F ✓
3	1		*Interior rear view mirror <i>Hec ?</i>	0.00	0.00	*180.00 F ✓?
4	1		*Interior rear view mirror cover <i>Hec ?</i>	0.00	0.00	*50.00 F ✓?
5	1		*Windscreen Gum <i>Hec</i>	0	0.00	*60.00 FS ✓
6	1		*ERP bracket <i>Hec</i>	0	0.00	*26.00 FS ✓
Sub Total (\$\$)						1,066.00
+ Margin on L,N Items 10.00% (\$\$)						98.00
Total Parts (\$\$)						1,164.00

F=Franchise part, S=SpcNett.

Vin's Motor Pte Ltd/SGU9933E/27/01/2023 16:36. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO SPRAY PAINTING	New	500.00 300/-
<u>Labour Items</u>			
2	To REMOVE AND REPLACE FRONT WINDSCREEN	New	120/- 180.00 80/-
3	To remove and refix roof lining	New	200/- 380.00 200/-
4	TO REPAIR DAMAGES	New	200/- 380.00 200/-
Gross Labour Cost (\$\$)			1,440.00

Vin's Motor Pte Ltd/SGU9933E/27/01/2023 16:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

30/01/2023 @ 130hrs

Not Antwigh

? Part. Excess TBA

T Ryan 3 days.

LKK Auto

8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: