



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BONNIE KWOK LLC 101A UPPER CROSS STREET #08-12 PEOPLE'S PARK CENTRE SINGAPORE 058358		Ref: CS/LAW23000857/Tqy3m4 Date: 15/05/2023 Code: L094	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	YN 8137S	Veh. Inspected	SMU 6645K(SMZ 8383B)
Policy No.		Coverage (\$)	0.00
Claim No.	BK.20319.21.P	Excess (\$)	0.00
Assign From	NAZIRAH SALLEH	Assign Date	20/01/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	W1N1569422J696621	Colour	GREY
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50R18	CONTINENTAL	6 mm
L/H Front Tyre	235/50R18	CONTINENTAL	6 mm
R/H Rear Tyre	235/50R18	CONTINENTAL	6 mm
L/H Rear Tyre	235/50R18	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	25/01/2021	Inspection Date	02/11/2022
Survey held at	CARPARK OF 823A TAMPINES ST 81 SINGAPORE 521823		
Repairer	XIN YUN AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	