

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: HL Assurance Pte Ltd  
11 Keppel Road  
#11-01 ABI Plaza  
Singapore 089057

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Goh Siew Geok (Janice)

Date: 14 Feb 2023

**Preliminary Advice**

Vehicle No	: SLB3715Z	Accident Date	: 13/01/2023
Make	: VOLKSWAGEN GOLF	Policy No.	: MP317255
Assignment Date	: 30/01/2023	Excess	: S\$300.00
Date of Inspection	: 09/02/2023	Est. Duration of Repair	: 4
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,144.00
Revised Amount	:S\$	2,390.00
Check Items (Estimated)	:S\$	484.00
Total	:S\$	2,874.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	19,929.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,071.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.