

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/AIG23000874/4p3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31 involved in acc on 29-02-2024

net \$1389

submit report.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

NO. : 42643

DATE : 27/01/2023

CLAIM NO. : 12099

POLICY NO. : 300446358

FROM : RAYMOND

VEHICLE NO. : FX9274U
MAKE/MODEL : HON / WAVE 125R A

*not authorized
here
30/1/23
2/5
4 days
Zhanghua after 10pm*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 29554 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
2	BAR HANDLE P/N: 28897 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00
3	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$239.00	239.00
4	BRACKET UNDER FORK P/N: 24880 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$262.00	262.00
5	CALIPER BRAKE FRONT ASSY P/N: 24839 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$190.00	190.00
6	COVER BODY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$90.00	90.00
7	COVER FRONT UPPER P/N: 62008 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00
8	COVER LEG SHIELD INNER RH P/N: 35278 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
9	COVER WINDSHIELD LOWER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$72.00	72.00

*42643

*

100%

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	COWLING FRONT ASSY P/N: 62007 - (REPORTED BY MECHANIC)	cu) REPLACE	1.00	\$45.00 ✓	45.00
11	FOOTREST FRONT P/N: 26780 - (REPORTED BY MECHANIC)	To.1 REPLACE	1.00	\$35.00 ✓	35.00
12	FORK FRONT ASSY LH P/N: 24844 - (REPORTED BY MECHANIC)	Sn REPLACE	1.00	\$259.00 X	259.00
13	FORK FRONT ASSY RH P/N: 24843 - (REPORTED BY MECHANIC)	Sn REPLACE	1.00	\$259.00 X	259.00
14	GRIP HANDLE LEFT - (REPORTED BY MECHANIC)	To.1 REPLACE	1.00	\$21.00 ✓	21.00
15	GRIP HANDLE SET (HMA) RH & LH P/N: 36507 - (REPORTED BY MECHANIC)	ren REPLACE	1.00	\$16.00 ✓	16.00
16	HEADLAMP P/N: 23957 - (REPORTED BY MECHANIC)	sen REPLACE	1.00	\$50.00 ✓	50.00
17	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	A Supply/Install	8.00	\$85.00 280	680.00
18	LAMP SIGNAL FRONT LH P/N: 30766 - (REPORTED BY MECHANIC)	17 REPLACE	1.00	\$25.00 X	25.00
19	LAMP SIGNAL FRONT RH P/N: 54719 - (REPORTED BY MECHANIC)	17 REPLACE	1.00	\$25.00 X	25.00
20	LEVER BRAKE P/N: 24840 - (REPORTED BY MECHANIC)	Bro REPLACE	1.00	\$20.00 ✓	20.00
21	MIRROR RH P/N: 31362 - (REPORTED BY MECHANIC)	cu7 REPLACE	1.00	\$28.00 ✓	28.00
22	MUDGUARD FRONT (RED) P/N: 29222 - (REPORTED BY MECHANIC)	cu7 REPLACE	1.00	\$68.00 ✓	68.00
23	MUFFLER assy - (REPORTED BY MECHANIC)	REPLACE	1.00	\$620.00 ?	620.00
24	PEDAL BRAKE P/N: 23959 - (REPORTED BY MECHANIC)	Ben REPLACE	1.00	\$45.00 ✓	45.00

*42643 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	RUBBER FOOTREST FRONT P/N: 27373 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00
26	SHAFT MAINSTAND P/N: 23962 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
27	SHOCK ABSORBER REAR YSS - (REPORTED BY MECHANIC)	REPLACE	1.00	\$143.00	143.00
28	STEERING CONE SET P/N: 30839 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	70.00
29	TRANSPORT CHARGES P/N: 07169 - ONE WAY TOWING		1.00	\$65.00	65.00
SUB TOTAL					\$3,490.00
GST @ 8 %					\$279.20
GRAND TOTAL (SGD)					\$3,769.20

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

518

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*42643 *

bizSAFE₃

