

ASS. REC. BY:

REF:

ASM/23000875/Kp

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop n/vs _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 845k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 02 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

3/2 21/2p @ 850k @ 02 days (Red \$2,105.00/71%)

Veh No: SKX 8004TYr Regn: 12, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy WishColour: M. GreySp. Reading: 142573

Eng/No: _____

C/No: STD 64 20W 80J 003442Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 20/1/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / H/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 2/2/2023

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: 02

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. _____

Fees: _____

Others: _____

TOTAL: _____

Add Fee: ☐

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Report Format: TP

Lump Sum / I.B.I: (\$ 4/5 \$850.00)

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5, Singapore 568047
Tel : 64810304 Fax : 64815587
Reg No : 200600989K

AXA Insurance Singapore Pte Ltd

Motorcar Claim Department

Attn: Claim Officer

Estimate Repair

Date : 1/2/2023

Accident Involving SKX6004T & SHA2344U On 20/01/2023

*NOT Withheld
11 Lm 8850h
Recovery After Pain*

Item	Descriptions	Amount
1	Rear Bumper	
2	Rear Bumper Reinforcement	
3	Rear End Panel	
	Repair	
	Repair	

2 days
Total For Parts (Less 10%) \$ 595.00

S/N Item (s)

1	Bumper Clips - 1 Set	
2	Rear Parking Sensor	

Short
Total For S/N \$ 235.00

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel	
	Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	
3	To Check Wiring For Proper Function	

Total For Parts & Labour \$ 2,955.00

Ready Auto Care Pte Ltd

Sulynn - 96606551

No Of Days For Repair *4 Days*

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

Illegal modification(s) is allowed

Expenditure item(s) must be resurveyed and

Final approval from Insurance Company

By Repairer