

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

T P Budget Direct
x low Chn.

JEMIX HEAT TREATMENT (S) PTE LTD
101 UPPER CROSS ST #06-11
SINGAPORE 058357

TAX INVOICE

Repair Code : CLM15787

Date in : 20/01/2023

Vehicle Num. : SKM7045B

Model : TOYOTA COROLLA ALTIS 1.6L CVT

Chassis/Eng# : MR053REH104002222/1ZRX401620

Contact : 97525765

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>repld</i>	1	589.50	✓ 589.50
REAR BUMPER END SEAL COVER RH <i>repld</i>	1	58.50	✓ 58.50
REAR BUMPER REINFORCEMENT <i>new</i>	1	423.90	+ 423.90
REAR BUMPER RH REFLECTOR <i>repld</i>	1	63.40	✓ 63.40
REAR BUMPER SIDE RETAINER L/R <i>RH repld</i>	2	116.00	45 232.00
REAR RH FENDER <i>Dented</i>	1	1218.20	✓ 1,218.20
REAR RH SPORT RIM <i>lit</i>	1	2133.00	80/sv 2,133.00
REAR RH TAILLAMP <i>repld</i>	1	402.80	✓ 402.80
REAR RH TAILLAMP LOWER BRACKET <i>repld</i>	1	64.00	✓ 64.00
Subtotal before discount			5,185.30
Percentage discount 25%			1,296.33
Sub-total 1			3,888.98
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30 80.00
REAR RH TAILLAMP CLIPS - SET <i>new</i>	1	25.00	10 25.00
REAR WINDSCREEN SEAL <i>3 per</i>	1 <i>120</i>	80.00	40 80.00
REAR WINDSCREEN SEALANT	1	80.00	40 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

JEMIX HEAT TREATMENT (S) PTE LTD
101 UPPER CROSS ST #06-11
SINGAPORE 058357

Contact : 97525765

TAX INVOICE

Repair Code : CLM15787
Date in : 20/01/2023
Vehicle Num. : SKM7045B
Model : TOYOTA COROLLA ALTIS 1.6L CVT
Chassis/Eng# : MR053REH104002222/1ZRX401620

Subtotal before discount	265.00
Percentage discount 0%	0.00
Sub-total 2	265.00
Parts-total	4,153.98

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
To remove, reinstall windscreen (REAR)
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,430.00
Parts & Labour Total	6,583.98

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

60 80.00
1500 120 150.00
60 100.00
600 1,000.00
600 1,000.00
60 100.00
Adnan
L/S 02/02/23
05 Prys
total: 4251.05
L/S : 3.4K.