



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE			Ref: CC4/ASM23000890/Tpa3q2 Date: 19/04/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SH 8217Y	<b>Veh. Inspected</b>	JTL 3910
	<b>Policy No.</b>	P2478218	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	S3M04IHV	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	30/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	YAMAHA 135LC	<b>c.c</b>	134
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
	<b>Chassis No.</b>	PMYUG0810K0107961	<b>Colour</b>	BLACK/SILVER
	<b>Odometer</b>	56525 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	70/90 R17	CORSA	5 mm
	<b>L/H Front Tyre</b>			mm
	<b>R/H Rear Tyre</b>	90/80 R17	CORSA	5 mm
	<b>L/H Rear Tyre</b>			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION & N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	10/01/2023	<b>Inspection Date</b>	30/01/2023
	<b>Survey held at</b>	SXZ MOTOR PTE LTD 61 WOODLANDS INDUSTRIAL PARK E9 #01-13, E9 PREMIUM, SINGAPORE 757047		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	