

CS/ASM 23.000 89.0/Typ 3

Others



SXZ MOTOR FIELD LTD

UEN: 202106993H

61 Woodlands Industrial Park E9.

#01-13. Singapore 757047

Hp: 82987265

Email: sxzmotor@gmail.com

Name : _____

Bike No : J7L3910

Model : _____

REPAIR CHECKLIST

NO:	PARTICULARS	QTY	UNIT PRICE	AMOUNT	P	C
1	Fork Left/Right	01	\$180	\$180	phk?R	
2	7-Fork Bracket	01	\$180	\$180	SN 120	
3	Handlebar	01	\$90	\$90	phk	
4	cone Bearing	01	\$80	\$80	phk	
5	cover set	01	\$280	\$280	dis	
6	Headlamp	01	\$80	\$80	ant	
7	Signal lamp console left/right	02	\$40	\$80	ant	
8	Headlamp Inner Panel	01	\$50	\$50	phk/dis	
9	Swingarm	01	\$280	200 \$280	phk	
10	Pillion Bar	01	\$40	\$40	ant	
11	Basket Front	01	\$25	\$25	ant	
12	Labour	01	\$150	\$150	✓	
13				Part 925		
14				0/- \$32.50		
15				SN 270		
16				1102.50		
17				L/S \$900		
18				03 days		
19						
20						

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749/62563561

NP 30/1/23 3pm 03 days

L/S Resurvey after repair

taufik@lkkauto.com