

SJC 55186.

Subaru Outback.

JF2BS9KC2FG003691

TP Liberty.
veron.

Rear Bumper	Dehead	694.50 ✓
Rear Bumper Clips	per	30(SN) ✓
Rear Bumper Side Holder x12	per	34.5 x 2 = 69 ✓
Rear Bumper Reinforcement.	NP per	433.40 x
Reverse Sensor	Demogd	280(SN) 200(SN)
Rear End Panel	Rep's	359.20 +
Rear End Panel Top Garnish	per	142.70 +
Rear End Panel Top Garnish Clips.	NP per	20(SN) +
Rear End Panel Sealant.		60(SN) x.
Tailgate	Rep's	1072.80 +
Tailgate Lock.	NP per	325.10 +
Tailgate Reflector LH.	Ordered	250.40 ✓
Tailgate Outer Garnish	Ordered	398.40 ✓
Tailgate Outer Garnish Clips	per	20(SN) ✓

SJC55186.

Tailgate Glass Moulding	} Not over	149.40	+
Tailgate Glass Sealant		60(SN)	+
Subaru Logo	} New	52.90	✓
Subaru Wording.		48.20	✓
HWD Wording.		54.10	✓
Outback Wording		50.40	✓
Tailgate LH. Guard		460.80	✓

2078.80

1663.04

S.N: 230

STC 55186

Panel Beating

Spray Painting.

Wiring.

To apply tuffcoat.

To remove reverse sensor.

To remove rear camera

To transfer tailgate fitting.

To remove tailgate glass

To remove upholstery.

~~1000~~ 400

~~1000~~ 500

~~50~~ 30

~~150~~ 30

~~100~~ 50

~~100~~ +

150 +

180 + 1010

150. +

total: 2903.04

L/s: 2.3K

0.3 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: