



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

not Authorised
Mr

30/1/23

D.O.A : 18TH JANUARY 2023

30th January 2023

OWNER : OCL BUILDING SERVICES PTE LTD

2/5 @ 600
2 days

REG. NO. : GBA 7557 K

MAKE/MODEL : TOYOTA DYNA

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMOUNT(\$\$)
<u>LIST ITEMS</u>		
1	Rear Tailgate	\$ 11 1,945.20 X
2	Rear Tailgate Latch	\$ 11 390.00 X
2	Rear Tailgate Side Member with Rubber	\$ 11 536.00 X
2	Rear Tailgate Hinges	\$ 11 136.00 X
1	Rear Tailgate Lower Member	\$ 11 749.40 X
2	Rear Taillamps	288.50 1/5 @ 11 \$ 2/side 750.00 1/2
2	Rear Taillamp Brackets	\$ 11 238.40 X
1	Rear Number Plate Bracket	\$ 11 155.00 X
1	Rear Number Lamp	\$ 11 175.00 X
1	Rear Tire Carrier	\$ 11 385.00 X
		\$ 5,460.00
	LESS 25%	\$ 1,365.00
		\$ 4,095.00
<u>SPECIAL NETT ITEMS</u>		
1	Rear "13PAX" Sticker	\$ 11 35.00 X
1	Rear "70KM/H" Sticker	\$ 11 35.00 X
1	Reverse Sensor	\$ 11 280.00 X
1	Rear Number Plate	\$ 11 35.00 20
		\$ 385.00
<u>LABOUR CHARGES</u>		
1	To remove, replace & check up wiring	\$ 50.00 20
3	To rust proof affected areas	\$ 11 200.00 X
9	Panel Beating	\$ 1,200.00 300
10	To re-spray the affected areas	\$ 1,000.00 200

\$ 2,450.00

\$ 6,930.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: