

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/AIG 23000895/4293

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$))

16/2/23 4/5 3500 indmt Anyss

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3611 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 96961519

YEO AI LING BELINDA (YANG AILING)
BLK 813 TAMPINES STREET 81
#11-552
SINGAPORE 520813
TEL : FAX :
PH : 96961519
ATTN :

ESTIMATE BILL

Number : EB00006185
Date : 30/1/2023
Case No : AD00013553
Vehicle No : SLD9552B
Chassis : GK31217914
Year of Mfr : 2016
Policy No : 5101315507-04
Model : HONDA FIT 1.3G F
PACKAGE A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BONNET ✓ <i>Bu C</i>	1.0	575.90	20	460.72
2	BONNET HINGE RH X <i>11</i>	1.0	40.00	20	32.00
3	BONNET HINGE LH X <i>11</i>	1.0	40.00	20	32.00
✓4	SUPPORT PANEL <i>Self</i>	1.0	420.80	20	336.64
5	SUPPORT PANEL TOP GARNISH <i>11</i>	1.0	28.00	20	22.40
6	SUPPORT PANEL INNER CENTER GARNISH LH <i>11</i>	1.0		20	
7	RADIATOR <i>11</i> X	1.0	1,250.00	20	1,000.00
8	RADIATOR COWLING <i>11</i>	1.0	125.00	20	100.00
9	RADIATOR FAN <i>11</i>	1.0	65.00	20	52.00
10	RADIATOR MOTOR <i>11</i>	1.0	362.90	20	290.32
✓11	AIR CON CONDENSER <i>Part</i>	1.0	810.00	20	648.00
12	FRONT GRILLE ASSEMBLY <i>one</i>	1.0	356.00	20	284.80
13	FRONT BUMPER ✓ <i>De</i>	1.0	904.70	20	721.36
14	FRONT BUMPER RETAINER LH <i>Best</i>	1.0	15.00	20	12.00
15	FRONT BUMPER RETAINER RH <i>Self</i>	1.0	15.00	20	12.00
16	FRONT BUMPER BRACKET RH <i>11</i>	1.0	30.90	20	24.72
17	FRONT BUMPER BRACKET LH <i>11</i>	1.0	30.90	20	24.72
✓18	FRONT BUMPER REINFORCEMENT <i>R</i>	1.0	246.70	20	197.36
19	FRONT BUMPER LOWER GARNISH <i>For</i>	1.0	30.90	20	24.72
20	FRONT BUMPER SIDE GRILLE RH <i>mis</i>	1.0	30.90	20	24.72
✓21	HEADLAMP LH <i>one</i>	1.0	583.50	20	466.80
✓22	HEADLAMP RH <i>one</i>	1.0	583.50	20	466.80
✓23	HEADLAMP BRACKET RH <i>one</i>	1.0	35.00	20	28.00
✓24	HEADLAMP BRACKET LH <i>one</i>	1.0	35.00	20	28.00
List Price - Parts Sub Total					5,290.08
25	FRONT FENDER LH - REPAIR <i>2 X</i>	1.0			
26	FRONT FENDER RH - REPAIR <i>2 X</i>	1.0			
27	FRONT NUMBER PLATE <i>Self</i>	1.0	30.00	0	20 30.00
28	FRONT NUMBER PLATE HOLDER <i>Self</i>	1.0	30.00	0	20 30.00
29	RADIATOR COOLANT X <i>11</i>	1.0	180.00	0	180.00
Special Nett Price - Parts Sub Total					240.00
Parts Total					5,530.08
30	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 96961519

YEO AI LING BELINDA (YANG AILING)
BLK 813 TAMPINES STREET 81

#11-552

SINGAPORE 520813

TEL : FAX :

PH : 96961519

ATTN :

ESTIMATE BILL

Number : EB00006185

Date : 30/1/2023

Case No : AD00013553

Vehicle No : SLD9552B

Chassis: GK31217914

Year of Mfr 2016

Policy No 5101315507-04

Model : HONDA FIT 1.3G F
PACKAGE A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
31	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
32	ANTI-RUST COATING	1.0	150.00	0	150.00
33	TO SERVICE & TOP-UP AIR-CON GAS	1.0	180.00	0	180.00
Labour 1 Sub Total					2,130.00
SINGAPORE DOLLARS : EIGHT THOUSAND TWO HUNDRED SEVENTY-TWO AND CENTS EIGHTY-NINE ONLY					0.00
Less Excess					0.00
SUBTOTAL					7,660.08
GST 8.00%					612.81
TOTAL					8,272.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of accident : 22/01/2023 02:50 PM. Place : BEDOK RESERVOIR ROAD > BEDOK RESERVOIR VIEW

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE