

From: Lok, Jasmine <jasmine.lok@sg.gaig.com>
Sent: Friday, 3 March 2023 2:24 PM
To: Renee Sia (LKK Auto)
Cc: SUR
Subject: Survey Report & Invoice of Vehicle SMD 760P Ref: CLMOMVP000001290
Attachments: GAI-LKKInvoice-AC2301256.pdf; GIA RPT.pdf; LKKAdjustment.pdf; LKKInspection.pdf; LKKPhoto.pdf; Resurvey Photo-1.pdf; SUPPLEMENTARY.pdf

Dear Renee,

We refer to our conversation just now.

We would like to request before and after photos of the

- 1) UNBEKANNT REAR BOOT LID *necessary item must replace* 8880
- 2) HIGH-MOUNT 3RD BRAKELIGHT *- see (must replace) which can remove required to be replaced*
- 3) COVER FOR REAR BUMPER (LOWER) *at 8896 & 8897*

Thank you

Best Regards

Jasmine Lok, Claims | P. +65 6804 6059 | F. +65 6235 3354 jasmine.lok@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190

For more information on our financial ratings, visit [GAIG.com/FinancialStrength](https://www.gaig.com/FinancialStrength).



A+ (Superior)
Affirmed December 3, 2021

Moody's
A1 (Good)
Published April 2022

Standard & Poor's
A+ (Strong)
Affirmed March 8, 2022

Thank you for your trust in us. We're proud to continue to serve you during this unprecedented time. As COVID-19 continues to affect us all, we assure you that we remain committed to providing the high level of service you deserve. [Read more.](#)

From: Renee Sia (LKK Auto) <reneesia@lkkauto.com>
Sent: 02 March 2023 4:45 PM
To: Wong, Shery <shery.wong@sg.gaig.com>
Cc: Motor Claims <motorclaims@sg.gaig.com>; SUR <sur@lkkauto.com>
Subject: [External] Survey Report & Invoice of Vehicle SMD 760P Ref: CLMOMVP000001290

Dear Shery,
Enclose Survey Report of SMD 760P.
Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 760P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	UNBEKANNT REAR BOOT LID (SN)	BENT	4,850.19	4,850.19
2	1K WINDOW ADHESIVE @\$50.73 (SN)	NECESSARY	101.46	101.46
1	ALL PURPOSE CLEANER (SN)	NECESSARY	84.67	84.67
1	PRIMER (SN)	NECESSARY	24.91	24.91
1	ACTIVATOR (SN)	NECESSARY	21.62	21.62
2	APPLICATOR @\$9.19 (SN)	NECESSARY	18.38	18.38
2	RIVETTED CAP NUT @\$2.81 (SN)	NECESSARY	5.62	5.62
1	UNBEKANNT EMBLEM - SKODA (SN)	NECESSARY	99.13	99.13
1	INSCRIPTIO NAME PLATE - SKODA (SN)	NECESSARY	75.51	75.51
1	LETTERING NAME PLATE - KODIAQ (SN)	NECESSARY	110.32	110.32
1	HOOD LATCH BOOT LID LOCK (SN)	NOT NECESSARY	236.07	-
1	BUMP STRIP BUMPER UPPER GRILLE (SN)	NOT NECESSARY	262.50	-
1	COVER FOR REAR BUMPER (UPPER) (SN)	TO REPAIR SEE LABOUR	2,208.62	-
1	COVER FOR REAR BUMPER (LOWER) (SN)	CUT	473.82	473.82
1	SENSOR BRACKET (SN)	NECESSARY	19.51	19.51
1	SENSOR BRACKET (SN)	NECESSARY	19.51	19.51
1	SENSOR BRACKET (SN)	NECESSARY	15.25	15.25
1	SENSOR BRACKET (SN)	NECESSARY	15.25	15.25
1	SENSOR BRACKET (SN)	NECESSARY	15.25	15.25
1	SENSOR BRACKET (SN)	NECESSARY	15.25	15.25
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	84.64	84.64
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	74.37	74.37
2	DOUBLE COLLARED STUD @\$9.93 (SN)	NOT NECESSARY	19.86	-
2	SHOULDERED NUT @\$3.38 (SN)	NECESSARY	6.76	6.76
1	FORM REINF REINFORCEMENT (SN)	NOT NECESSARY	149.31	-
1	RETAINING BUMPER CTR BRACKET (SN)	NOT NECESSARY	92.64	-
1	GUIDE PLEC LHR BUMPER BRACKET (UPPER) (SN)	NOT NECESSARY	57.96	-
1	GUIDE PLEC RHR BUMPER BRACKET (UPPER) (SN)	NOT NECESSARY	57.96	-
1	GUIDE PLEC LHR BUMPER BRACKET (SIDE) (SN)	NOT NECESSARY	57.96	-
1	GUIDE PIEC RHR BUMPER BRACKET (SIDE) (SN)	NOT NECESSARY	57.96	-
1	REAR NUMBER PLATE (SN)	SCRATCHED	80.00	80.00
1	HIGH-MOUNT 3RD BRAKELIGHT (SN) (ADDITIONAL)	NECESSARY	186.64	186.64
			9,598.90	6,398.06

Report Ref No. CS/GAI23000897/Rvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR.		280.00	280.00
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
	LABOUR. INCLUSIVE OF THE REPAIR OF COVER FOR REAR BUMPER (UPPER).		4,200.00	1,680.00
	SPRAY PAINT.		3,200.00	1,600.00
	R&R REAR W/SCREEN.		840.00	840.00
	TRANSFER BOOT LID MECHANISM.		840.00	420.00
	REAR WATER LEAK TEST.		150.00	150.00
			9,990.00	5,450.00
	GRAND TOTAL		19,588.90	11,848.06
RECOMMENDED COST OF REPAIRS				11,848.06

Report Ref No. CS/GAI23000897/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

Boothal




ŠKODA

ETKA

Model	Year	MG	SG	Illustration	Restrictions	UPD	10:41	07.03.2023
KOD	2018	8	27	827-000		1024		

EC	TC	ITC	VIN	Production	Sales Type
CZEA	SYT	AD	TMBKC7NS7J8095713	12.06.2018	NS73LC

FI SUGGESTION






SKODA

ETKA

Model	Year	MG	SG	Illustration	Restrictions	UPD	10:42	07.03.2023
KOD	2018	8	07	807-050		1024		
EC	TC	ITC	VIN			Production	Sales Type	
CZEA	SYT	AD	TMBKC7NS7J8095713			12.06.2018	NS73LC	

FI SUGGESTION



Per Lim

According to our survey,

1.) _____ is the new boot lid. See photo below.
0414.

2.) _____ - this is a necessary item when boot lid
is replaced because it is glued into
the new boot lid and once removed, the
moulding will break. See photo below
0427, 0430

3.) _____ is the new bumper lower which was
cut. The replaced See photo below
for the replacement.
0415