

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sundari Nagarajan

Date: 08 Feb 2023

Preliminary Advice

Vehicle No	: SJL3113G	Accident Date	: 14/01/2023
Make	: MERCEDES-BENZ E250	Policy No.	: D22MPC0008471
Assignment Date	: 30/01/2023	Excess	: S\$750.00
Date of Inspection	: 01/02/2023	Est. Duration of Repair	: 5
Inspection At	: BODYFIX (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2, #04-06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,985.50 (Est \$17,775.50 + Supp \$1,210.00)
Revised Amount	:S\$	7,833.50 (incl Supp \$1,210.00)
Check Items (Estimated)	:S\$	8,932.00
Total	:S\$	16,765.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	42,393.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,607.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on Supplementary Items. The repairer agreed to repair the vehicle not more than \$16,000.00.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.