

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC23000905/Swy3m4
	300 BEACH ROAD #17-04/07 THE CO) NCOURSESINGAPORE 199555		Date:	08/03/2023
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBB 8061L	Veh. Inspected	ı	SNF 1814P
	Policy No.		Coverage (\$)		0.00
	Claim No.	22/23/23/VC05/026897	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		30/01/2023
2.	. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c		1798
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	JTDZS3EU00J034142	Colour		BLUE
	Odometer	115550 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/55 R16	TERAFLEX		6 mm
	L/H Front Tyre	205/55 R16	TERAFLEX		6 mm
	R/H Rear Tyre	205/55 R16	TERAFLEX		6 mm
	L/H Rear Tyre	205/55 R16	TERAFLEX		6 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S REAR PORTION.			
5.	General Information				
	Accident Date	27/01/2023	Inspect Date /	Time	13/02/2023 (12:00 PM)
	Survey held at	GARAGE 13 PTE LTD			
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.			
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC23000905/Swy3m4

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser