

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A16 23000910/4 ps3.**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

89500

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

11/5/23Nett 87324
Side Tow out alreadyVeh No: FBP1194J

Yr Regn:

10/02/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

CB150R c.c

149

Colour:

Green

A/C:

Insured / Std / NI / NA

Sp. Reading

40433

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MLHKC2884J5031582Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 100 / 50 R17
R: 150 / 60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

25/01/23

D.O.I.

31/1/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

NO. : 42658

DATE : 30/01/2023
CLAIM NO. : 12101
POLICY NO. : 300574490

FROM : RAYMOND

VEHICLE NO. : FBP1194J
MAKE/MODEL : HON / CB150R

*not allowed
31/1/23
L/S
4 days
change the up*

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE REAR WHEEL P/N: 74241 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00 ?
2	BALANCER HANDLE P/N: 66879 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	CU? 18.00
3	BAR HANDLE P/N: 71190 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$95.00	95.00 ?
4	BOLT HEX CAP P/N: 71847 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00 ?
5	BOLT-WASHER SIGNAL 5X25 P/N: 76582 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	? 13.00 ?
6	BOX REAR (KAPPA) K35N W/O LIGHT BLACK P/N: 26032 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$280.00	CU? 280.00
7	BRACKET (HD) BOX REAR P/N: 61194 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$203.00	Sub 203.00
8	BRACKET FOOTREST P/N: 74250 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	Sub 34.00
9	BRACKET FOOTREST REAR RH P/N: 74228 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	CU? 56.00

*42658 *

bizSAFE₃



Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
10	COLLAR LAMP SIGNAL P/N: 74251 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
11	COLLAR SPROCKET REAR P/N: 76566 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
12	COLLAR STEP LOWER P/N: 71848 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	8.00
13	COVER FENDER LOWER REAR P/N: 76581 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00
14	COVER LICENSE LIGHT(WL) P/N: 76570 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00
15	COVER SIDE UPPER RH P/N: 74856 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00	36.00
16	COVER UNDER RH P/N: 74222 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00	36.00
17	FENDER REAR A P/N: 76577 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00	36.00
18	FOOTREST REAR RH P/N: 74266 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00	36.00
19	FOOTREST RH P/N: 48763 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$86.00	86.00
20	GRIP HANDLE RH P/N: 49673 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00
21	GUARD CHAIN P/N: 76567 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$39.00	39.00
22	HOLDER RH STEP P/N: 70993 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00
23	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING & INSTALLATION OF PARTS	Supply/Install	1.00	\$550.00	550.00
24	LAMP SIGNAL REAR LH P/N: 76574 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$75.00	75.00

*42658 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>		<u>Amount</u>
25	LAMP SIGNAL REAR RH P/N: 74236 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$90.00	<i>one</i>	90.00 ✓
26	LEVER BRAKE (SILVER) P/N: 71192 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	<i>set</i>	28.00 ✓
27	LICENSE LIGHT ASSY P/N: 76576 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$109.00	<i>one</i>	109.00 ✓
28	MASTER CYLINDER PUMP REAR P/N: 76568 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$109.00	<i>two</i>	109.00 ✓
29	METER IU (12V) NEW MODEL P/N: 34351 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$310.00	<i>one</i>	310.00 X
30	MIRROR LH ASSY P/N: 74269 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$62.00	<i>17</i>	62.00 X
31	MIRROR RH ASSY P/N: 71191 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$62.00	<i>one</i>	62.00 ✓
32	PEDAL BRAKE P/N: 70990 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.00	<i>set</i>	36.00 ✓
33	PIN SPLIT 1.6 FOOTREST P/N: 76572 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	<i>one</i>	8.00 ✓
34	PIN STEP BAR JOINT P/N: 76575 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	<i>one</i>	8.00 ✓
35	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	<i>set</i>	24.00 ✓
36	RIM SPORT FRONT P/N: 74258 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$565.00	<i>one</i>	565.00 ✓
37	RIM SPORT REAR ASSY P/N: 76580 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$613.00	<i>set</i>	613.00 ✓
38	RUBBER HANDLE P/N: 66882 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$13.00	<i>?</i>	52.00
39	RUBBER MOUNTING LAMP SIGNAL RH P/N: 74273 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	<i>two</i>	21.00 ✓

*42658 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price		Amount
40	SCREW TAPPING 4X16 LICENSE LIGHT P/N: 76569 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$13.00	?	26.00
41	SPRING FOOTREST RH P/N: 48757 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	mer	13.00
42	STAY FENDER REAR LH P/N: 76571 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	Bul	78.00
43	STAY FENDER REAR RH P/N: 76578 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	Bul	78.00
44	SWINGARM SUB ASSY P/N: 76579 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$698.00	?	698.00
45	TYRE 150/60-17 (PIRELLI) ROSSO 3 P/N: 72174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$183.00	pur	183.00
46	WASHER FOOTREST 15.5X27X2.0 P/N: 76573 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	mer	8.00

SUB TOTAL

\$5,057.00

GST @ 8 %

\$404.56

GRAND TOTAL (SGD)

\$5,461.56

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*42658 *

bizSAFE₃