

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23000911/DYA3Q2**Date:** 18/07/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0008003
Claimant Vehicle No :	SNK328G	Insured Vehicle No :	SLT1444Z
Date of Loss:	28/01/2023	Nature of Claim:	TP
		Claim No:	MFL2023D0001181

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNK328G		
Make & Model:	MERCEDES-BENZ CLA45 AMG, 2.0 (A)	Engine No:	13998060020618
Reg. Date:	22/12/2022 (Man. Year: 2021)	Chassis No:	W1K1183542N221973
Colour:	White	Odometer:	5439 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,736.90	3,159.30	33,577.60	91.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,840.00	690.00	9,150.00	92.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	46,576.90	3,849.30	42,727.60	91.74
+ GST 8.00/8.00% (S\$)	3,726.15	307.94	3,418.21	91.74
Nett Amount (S\$)	50,303.05	4,157.24	46,145.81	91.74
+ Car Rental (2.0 x S\$130.00/day) (S\$)		260.00		
+ Doc/Search Fee (S\$)		57.75		
+ Other Costs (S\$)		450.00		
Nett Liability (S\$)		4,924.99		

INSPECTION

Date of Assignment:	31/01/2023	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Date Inspected:	20/02/2023 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: BRYAN TANI**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	143	MERCEDES-BENZ CLA45 AMG 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNK328G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	3,127.00 FL	*- FL
2	1		*BOOTLID LOGO	Not Necessary	74.00 FL	*- FL
3	1		*BOOTLID AMG EMBLEM	Not Necessary	123.00 FL	*- FL
4	1		*BOOTLID CLA45S EMBLEM	Not Necessary	166.00 FL	*- FL
5	2		*BOOTLID NO. PLATE LAMP L+R	Not Necessary	196.00 FL	*- FL
6	1		*BOOTLID INNER TRIM	Not Necessary	563.00 FL	*- FL
7	2		*BOOTLID LAMP LH / RH	Not Necessary	1,672.00 FL	*- FL
8	1		*BOOTLID WEATHER STRIP	Not Necessary	399.00 FL	*- FL
9	2		*BOOTLID HINGE L+R	Not Necessary	348.00 FL	*- FL
10	2		*BOOTLID HINGE GARNISH L+R	Not Necessary	298.00 FL	*- FL
11	1		*BOOTLID LOCK	Not Necessary	349.00 FL	*- FL
12	1		*BOOTLID SWITCH	Not Necessary	298.00 FL	*- FL
13	1		*REAR WINDSCREEN MOULDING	Not Necessary	349.00 FL	*- FL
14	1		*REAR BUMPER	Distorted / Mtg Broken	2,797.00 FL	*1,885.00 FL
15	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	192.00 FL	*- FL
16	1		*REAR BUMPER LOWER SKIRTING	Distorted	1,955.00 FL	*1,280.00 FL
17	1		*REAR BUMPER CENTER CHROME	Not Necessary	417.00 FL	*- FL
18	2		*REAR BUMPER SIDE CHROME L+R	Not Necessary	508.00 FL	*- FL
19	4		*REAR BUMPER PARKING SENSOR	Not Necessary	1,522.00 FL	*- FL
20	4		*REAR BUMPER PARKING SENSOR HOLDING	Not Necessary	80.00 FL	*- FL
21	1		*REAR BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	1,433.00 FL	*- FL
22	1		*REAR BUMPER CENTER BRACKET	Not Necessary	330.00 FL	*- FL
23	2		*REAR BUMPER SIDE BRACKET L+R	Not Necessary	346.00 FL	*- FL
24	1		*REAR BUMPER UNDER COVER CENTER	Broken	410.00 FL	*262.00 FL
25	2		*REAR BUMPER UNDER COVER SIDE L+R	Not Necessary	478.00 FL	*- FL
26	1		*REAR BUMPER REINFORCEMENT	Not Necessary	1,506.00 FL	*- FL
27	2		*REAR BUMPER REINFORCEMENT BRACKET LH / RH	Not Necessary	318.00 FL	*- FL
28	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	79.00 FL	*- FL
29	2		*TAIL LAMP LH / RH	Not Necessary	1,962.00 FL	*- FL
30	2		*TAIL LAMP PANEL LH / RH	Not Necessary	958.00 FL	*- FL
31	2		*TAIL LAMP LOWER BRACKET LH / RH	Not Necessary	368.00 FL	*- FL
32	1		*REAR END PANEL	Not Necessary	1,558.00 FL	*- FL
33	1		*REAR END PANEL TOP GARNISH	Not Necessary	463.00 FL	*- FL
34	1		*REAR EXHAUST PIPE	Not Necessary	2,227.00 FL	*- FL
35	2		*REAR EXHAUST TIP LH / RH	Not Necessary	672.00 FL	*- FL
36	1		*REAR EXHAUST MUFFLER	Not Necessary	980.00 FL	*- FL
37	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	226.00 FL	*- FL
38	1		*REAR EXHAUST MOUNTING	Not Necessary	101.00 FL	*- FL
39	1		*DRIVER SEAT BELT	Not Necessary	1,680.00 FL	*- FL
40	1		*FRONT PASSENGER SEAT BELT	Not Necessary	1,671.00 FL	*- FL
41	1		*DRIVER SEAT BELT BUCKLE	Not Necessary	560.00 FL	*- FL
42	1		*FRONT PASSENGER SEAT BELT BUCKLE	Not Necessary	560.00 FL	*- FL
43	2		*REAR SEAT BELT LH / RH	Not Necessary	3,140.00 FL	*- FL
44	1		*SRS CONTROL MODULE	Not Necessary	1,882.00 FL	*- FL
45	1		*REAR NUMBER PLATE & CASING	Cracked	100.00 FS	*45.00 FS
46	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

7/18/23, 1:58 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BOOTLID CENTER CHROME CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
49	1		*REAR BUMPER CHROME CLIPS	Not Necessary	50.00 FS	*- FS
50	1		*REAR BUMPER UNDER COVER CLIPS	Necessary	50.00 FS	*15.00 FS
51	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
52	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
53	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
54	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					40,671.00	3,502.00
- List Item Discount on L Items 10.00/10.00% (S\$)					3,934.10	342.70
Total Parts (S\$)					36,736.90	3,159.30
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILIATE REPAIRS	New	400.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	4,000.00	300.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	3,000.00	200.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	120.00	0.00
7	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
8	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR ALL AFFECTED SEAT BELTS TO FACILITATE REPAIRS	New	300.00	0.00
10	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	1,000.00	150.00
Gross Labour Cost (S\$)			9,840.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >