

# TwinCar AUTOMOTIVE PTE LTD

**Company Registration and GST No. 200714616M**

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510 Fax: 67410510 Email: sales@n51.com.sg

Our Ref: **SLZ 1679 G**  
Your ref: **GBK 9476 U**

30 January 2023

**ALLIANZ INSURANCE SINGAPORE PTE LTD**

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

Attn: Motor Claims Department

Dear Sir/Madam,

**NAME OF CLAIMANT : TAN SOON HENG**  
**VEHICLE NUMBER : SLZ 1679 G**  
**YOUR INSURED VEHICLE NUMBER : GBK 9476 U**  
**ACCIDENT ON 20 JAN 2023 AT ABOUT 16:40 HOURS**  
**ALONG BENCOOLEN ST TWDS MIDDLE RD**

We refer to your email / fax dated **28 Jan 2023** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

**TWINCAR AUTOMOTIVE PTE LTD**

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-17

Singapore 417921

Contact Person: **6842 0051 / 6744 0510 (Melody)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



**Twincar Automotive Pte Ltd**

**FOR SURVEYOR:**

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor:

(Name & Signature):

Date & Time of Inspection: