

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TP Allianz
Xiao Tony

TAN SOON HENG

BLK 17 TELOK BLANGAH CRESCENT

#11-280

SINGAPORE 090017

TAX INVOICE

Repair Code : CLM15785

Date in : 20/01/2023

Vehicle Num. : SLZ1679G

Model : KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis/Eng# : KNAHU815VJ7206024/D4FDJH551932

Contact : 93821717

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented</i>	1	1098.00	✓ 1,098.00
FRONT RH DOOR BLACK TAPE - SET <i>new</i>	1	15.00	✓ 15.00
FRONT RH DOOR MECHANISM LOCK <i>new</i>	1	239.00	+ 239.00
FRONT RH DOOR WEATHER STRIP <i>new</i>	1	126.00	+ 126.00
REAR AXLE <i>new</i>	1	1170.00	+ 1,170.00
REAR BUMPER <i>Repair</i>	1	452.00	+ 452.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	25.00	+ 50.00
REAR RH DOOR <i>Distorted</i>	1	978.00	✓ 978.00
REAR RH DOOR BLACK TAPE - SET <i>new</i>	1	15.00	✓ 15.00
REAR RH DOOR CHECKER <i>new</i>	1	32.00	+ 32.00
REAR RH DOOR GLASS OUTER CHROME MOULDING <i>new</i>	1	53.00	+ 53.00
REAR RH DOOR GLASS REGULATOR <i>new</i>	1	207.00	+ 207.00
REAR RH DOOR GLASS REGULATOR MOTOR <i>new</i>	1	161.00	+ 161.00
REAR RH DOOR HINGE (LOWER) <i>new</i>	1	30.00	+ 30.00
REAR RH DOOR HINGE (TOP) <i>new</i>	1	30.00	+ 30.00
REAR RH DOOR INNER RUBBER STOPPER <i>new</i>	1	8.00	+ 8.00
REAR RH DOOR INNER TRIM BOARD <i>cracked</i>	1	697.00	✓ 697.00
REAR RH DOOR MECHANISM LOCK <i>Repaired</i>	1	267.00	✓ 267.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN SOON HENG
 BLK 17 TELOK BLANGAH CRESCENT
 #11-280
 SINGAPORE 090017

Contact : 93821717

TAX INVOICE

Repair Code : CLM15785

Date in : 20/01/2023

Vehicle Num. : SLZ1679G

Model : KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis/Eng# : KNAHU815VJ7206024/D4FDJH551932

REAR RH DOOR OUTER HANDLE <i>new</i>	1	48.00	+	48.00
REAR RH DOOR WEATHER STRIP <i>nt</i>	1	124.00	✓	124.00
REAR RH FENDER <i>Repair</i>	1	1349.00	+	1,349.00
REAR RH FENDER GLASS WITH CHROME MOULDING <i>new</i>	1	332.00	+	332.00
REAR RH FENDER INNER SHIELD <i>new</i>	1	262.00	+	262.00
REAR RH SHOCK ABSORBER <i>new</i>	1	200.00	+	200.00
REAR RH WHEEL BEARING <i>Damaged</i>	1	255.00	✓	255.00
Subtotal before discount				8,198.00
Percentage discount 10%				819.80
Sub-total 1				7,378.20
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	+	50.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR RH FENDER GLASS SEALANT <i>new</i>	1	80.00	+	80.00
REAR RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	+	50.00
REAR RH RIM <i>nt</i>	1	900.00	480/SW	900.00
Subtotal before discount				1,130.00
Percentage discount 0%				0.00
Sub-total 2				1,130.00
Parts-total				8,508.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN SOON HENG
BLK 17 TELOK BLANGAH CRESCENT
#11-280
SINGAPORE 090017

Contact : 93821717

TAX INVOICE

Repair Code : CLM15785

Date in : 20/01/2023

Vehicle Num. : SLZ1679G

Model : KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis/Eng# : KNAHU815VJ7206024/D4FDJH551932

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

X 60.00

To remove, reinstall fender glass

X 120.00

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

60 350.00

To road test driving, check and resetting wheel alignments system.

80 100.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 100.00

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

80 160.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1000 1,200.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

800 1,400.00

To apply anti-rust chemical on repaired and replaced panel.

50 120.00

Labour Total

3,610.00

Parts & Labour Total

12,118.20

*** This is a computer-generated document which requires no signature.***

page 3

Adrian
4/s 02/02/23.

06 Days.

total: 5930.40
1/s : 4.7K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: