



Case Details

Case Reference Number : TAX/01/23/2066
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4908U

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-20373-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 29/01/2023 12:50 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
Standard	Main			BUMPER FRT	1	602.60	602.60	25.00	451.95	Replace	1	451.95	Replace	✓	de ✓
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	✓	ue ✓
Standard	Main			BUMPER SUPPORT F/RH	1	86.20	86.20	25.00	64.65	Replace	1	64.65	Replace	✓	de ✓
Standard	Main			BUMPER ENERGY ABSORBER FRT	1	97.60	97.60	25.00	73.20	Replace	0	0.00	Check	✓	?
Standard	Main			BUMPER REINFORCEMENT FRT	1	567.90	567.90	25.00	425.92	Replace	0	0.00	Check	✓	?
Standard	Main			ARM SUB-ASSY,FR BUMPER LH	1	284.00	284.00	25.00	213.00	Replace	0	0.00	Not Give	✓	kur ✓
Standard	Main			ARM SUB-ASSY,FR BUMPER RH	1	284.00	284.00	25.00	213.00	Replace	0	0.00	Check	✓	?
Standard	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	389.90	389.90	25.00	292.42	Replace	0	0.00	Not Give	✓	kur ✓
Standard	Main			FOG LAMP RH	1	335.60	335.60	10.00	302.04	Replace	0	0.00	Not Give	✓	kur ✓
Standard	Main			BRACKET, FR TURN UPPER RH	1	32.30	32.30	25.00	24.22	Replace	0	0.00	Check	✓	?
Standard	Main			BRACKET, FR TURN CENTER RH	1	76.60	76.60	25.00	57.45	Replace	0	0.00	Check	✓	?
Standard	Main			BRACKET, FR TURN LOWER RH	1	34.40	34.40	25.00	25.80	Replace	0	0.00	Check	✓	?
Standard	Main			LENS & BODY, FR TURN RH	1	581.40	581.40	10.00	523.26	Replace	1	523.26	Replace	✓	cur ✓
Standard	Main			EMBLEM FRONT	1	98.70	98.70	25.00	74.03	Replace	1	74.03	Replace	✓	ue ✓
Standard	Main			GRILLE, RADIATOR	1	389.30	389.30	25.00	291.98	Replace	0	0.00	Not Give	✓	kur ✓
Total Spare Part Cost									6,406.90	Surveyor Total					2,308.70
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)					20.00
Final Spare Part Cost									5,125.52	Final Sur Total					1,846.96

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			GRILLE, RADIATOR LOWER NO.2	1	118.30	118.30	25.00	88.73	Replace	0	0.00	Not Give	fun
Standard	Main			BUMPER LIP FRT	1	182.70	182.70	25.00	137.02	Replace	0	0.00	Not Give	fun
Standard	Main			UNDER COVER SIDE/RH	1	52.50	52.50	25.00	39.38	Replace	0	0.00	Check	?
Standard	Main			UNDER COVER CENTER	1	511.20	511.20	25.00	383.40	Replace	0	0.00	Not Give	fun
Standard	Main			HEAD LAMP RH	1	1,075.40	1,075.40	10.00	967.86	Replace	1	967.86	Replace	cut
Standard	Main			SUPPORT RADIATOR, RH	1	72.00	72.00	25.00	54.00	Replace	0	0.00	Check	?
Standard	Main			WIPER WASHER JAR	1	236.90	236.90	25.00	177.68	Replace	0	0.00	Check	?
Standard	Main			MOTOR NO:1, WIPER WASHER JAR	1	315.70	315.70	10.00	284.13	Replace	0	0.00	Check	?
Standard	Main			MOTOR NO:2, WIPER WASHER JAR	1	317.10	317.10	10.00	285.39	Replace	0	0.00	Check	?
Standard	Main			FENDER FRT/RH	1	916.30	916.30	25.00	687.22	Replace	1	0.00	Repair	Rp
Standard	Main			NAME PLATE (HYBRID)	1	59.20	59.20	25.00	44.40	Replace	1	44.40	Replace	un
Standard	Main			FENDER LINER FRT/RH	1	195.40	195.40	25.00	146.55	Replace	1	146.55	Replace	fu
Standard	Main			FENDER LINER PAD, FR WHEEL, RH	1	56.30	56.30	25.00	42.22	Replace	0	0.00	Check	?
Total Spare Part Cost									6,406.90	Surveyor Total		2,308.70		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				
Final Spare Part Cost									5,125.52	Final Sur Total		1,846.96		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	1,014.00	300.00	
Total:			1,014.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200.00	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200.00	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00	
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0.00	REQ INVOICE
2	Main	TO WASH AND VACUUM	60.00	0.00	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	30.00	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
Total:			436.00	30.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	5,125.52	1,846.96
Total Labour Cost	1,014.00	300.00
Total Spray Painting	936.00	400.00
Other	436.00	30.00
Overall Total	7,511.52	2,576.96
Lump Sum Repair Option		☒
Lump Sum Total	7,500.00	2,600.00
Surveyor Approved Amount		2,600.00
No of Repair Days*	6	3
Remarks	-	REQ NBV / LUMPSUM REPAIR / AFTER PAINT PHOTOS FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR TAUFIKH. LG 9749 5749 (EMAIL)
Surveyor Name		Taufikh
Signature		
Survey Date	30/01/2023	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufikh 97495749
30/1/23 @ 3:55pm
45 mins after repair
taufikh c (WhatsApp)
03 days