

Date: 11/01/2023
Vehicle No: SLL1818X
Model: TESLA MODEL 3 RWD
Chassis: LRW3F7FS7NC571873-2022
Reg.Year: 2022

Third Party Insurer: AIG
Third Party Veh No: SDS8909D
Date of Accident: 02/01/2023
Estimator: NASHIK
Surveyor:

*Not within
3 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>nn</i> \$766.00
2	FRONT BUMPER PARKING SENSOR	1		<i>nn</i> \$163.55
3	FRONT BUMPER PARKING SENSOR BRACKET	1		<i>nn</i> \$4.67
4	FRONT FENDER LH	1		<i>/</i> REPAIR
SUB TOTAL				\$934.22
LESS 10%				\$93.42
PARTS TOTAL				\$840.80

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>nn</i> \$60.00
2	FRONT FENDER INNER SHIELD CLIPS LH	1		<i>nn</i> \$50.00
3	WRAPPING WORKS FOR AFFECTED AREAS	1		\$450.00
S/N TOTAL				\$560.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. \$600.00 *150*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT AREAS & ETC. \$600.00 *7*

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC. *nn* \$120.00 *X*

TO DIAGNOSIS FAULT CODE & RESET MEMORY. *nn* \$150.00 *X*

TO CHECK WIRING & ELECTRICAL SYSTEM. \$120.00 *20*

LABOUR TOTAL \$1,590.00

NASHIK TOTAL \$2,990.80

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

