



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/05/2023

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5586G
Case Reference Number	BUS/01/23/5006
Registration Date	24/11/2016
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	Muhamad Zulisham Bin Ahmad
Type of Accident	Side Swipe
Accident Date and Time	4/1/2023 11:53 AM
Accident Reported Date and Time	17/1/2023 9:39 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117527
Special Instruction to ARC,if any	SG5586G - Right front body damaged and right front light assembly broken SMH1631B (TP) -
Prepared Date and Time	18/1/2023 11:05 AM
Chassis Number	YV3S4P924GA179949
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,060.00
Total Spray Cost	\$602.00	\$432.00
Total Spare Part Cost	\$2,390.58	\$2,390.58
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,582.58	\$3,882.58
Lump Sum Total	\$0.00	\$3,900.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	Taufikh (LKK)
ARC / Surveyor Sign Off Date	19/01/2023 10:40 AM	30/01/2023 7:45 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/05/2023

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00				\$1,060.00		
Total Labour			\$1,590.00				\$1,060.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$602.00				\$432.00		
Total Spray Painting & Panel Beating			\$602.00				\$432.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012093			DOME,FRONT:LOWER,CLASS 2,FOR VOLVO B9TL	1.00	\$3,391.95	100.00	\$0.00	Repair	Repair
	Body	ATP-02795	O/S CORNER BUMPER	1.00	\$888.98	10.00	\$800.08	Replace	Replace
	Body	ATP-02804	O/S CORNER DEFLECTOR	1.00	\$328.33	10.00	\$295.50	Replace	Replace
	Body	ATP-02809	FRT O/S LIGHT BEZEL	1.00	\$298.28	10.00	\$268.45	Replace	Replace
6012141	VE	ELU-00312	HEADLAMP,BEAM:DIPPED,FOR VOLVO B9TL BUS	1.00	\$445.00	10.00	\$400.50	Replace	Replace
6012121	Body	A12-02429	BATTERY ACCESS DOOR	1.00	\$1,359.65	10.00	\$1,223.69	Replace	Replace
Total					\$6,712.19		\$2,988.22		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									