



**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/01/2023

User ID : JeongCH

Section A - Accident Details	
Registration Number	SG5586G
Case Reference Number	BUS/01/23/5006
Registration Date	11/24/2016
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	Muhamad Zulisham Bin Ahmad
Type of Accident	Side Swipe
Accident Date and Time	1/4/2023 11:53 AM
Accident Reported Date and Time	1/17/2023 9:39 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5586G - Right front body damaged and right front light assembly broken SMH1631B (TP) -
Prepared Date and Time	1/18/2023 11:05 AM
Chassis Number	YV3S4P924GA179949
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$602.00	\$0.00
Total Spare Part Cost	\$2,390.58	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$4,582.58</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	4.0	
Prepared / Adjusted By	Jeong Choon Hwee	3 days
ARC / Surveyor Sign Off Date	19/01/2023 10:40 AM	
Signature		
Remarks		

Tanpin 97495747  
up 30/1/23 @ 4pm  
c/s rising after repair  
Tanpin @ 16hamban  
3 days

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/01/2023

User ID : JeongCH

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	1060.
<b>Total Labour</b>	<b>\$1,590.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$602.00	432
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$602.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012093			DOME,FRONT,LOWER,C LASS 2,FOR VOLVO B9TL	1.00	\$3,391.95	100.00	\$0.00	Repair	Rp
	Body	ATP-02795	O/S CORNER BUMPER	1.00	\$888.98	10.00	\$800.08	Replace	an
	Body	ATP-02804	O/S CORNER DEFLECTOR	1.00	\$328.33	10.00	\$295.50	Replace	an
	Body	ATP-02809	FRT O/S LIGHT BEZEL	1.00	\$298.28	10.00	\$268.45	Replace	an
6012141	VE	ELU-00312	HEADLAMP BEAM DIPP ED, FOR VOLVO B9TL BUS	1.00	\$445.00	10.00	\$400.50	Replace	dis
6012121	Body	A12-02429	BATTERY ACCESS DOOR	1.00	\$1,359.65	10.00	\$1,223.69	Replace	bt
<b>Total</b>					<b>\$6,712.19</b>		<b>\$2,988.22</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									