

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 30/01/2023

User ID : JeongCH

Section A - Accident Details

Registration Number	SG5586G
Case Reference Number	BUS/01/23/5006
Registration Date	11/24/2016
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	Muhamad Zulisham Bin Ahmad
Type of Accident	Side Swipe
Accident Date and Time	1/4/2023 11:53 AM
Accident Reported Date and Time	1/17/2023 9:39 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5586G - Right front body damaged and right front light assembly broken SMH1631B (TP) -
Prepared Date and Time	1/18/2023 11:05 AM
Chassis Number	YV3S4P924GA179949
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$602.00	\$0.00
Total Spare Part Cost	\$2,390.58	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,582.58	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	19/01/2023 10:40 AM	
Signature		x
Remarks		

Taufik 97495747
up 30/1/23 @ 4pm
c/s Rising after repair
Taufik @ 16hamban
3 days

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/01/2023

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	1060 ✓
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$602.00	432 ✓
Total Spray Painting & Panel Beating	\$602.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012093			DOVE, FRONT LOWER, CLASS 2, FOR VOLVO B9TL	1.00	\$3,391.95	100.00	\$0.00	Repair	Rp
	Body	ATP-02795	O/S CORNER BUMPER	1.00	\$888.98	10.00	\$800.08	Replace	an
	Body	ATP-02804	O/S CORNER DEFLECTOR	1.00	\$328.33	10.00	\$295.50	Replace	an
	Body	ATP-02809	FRT O/S LIGHT BEZEL	1.00	\$298.28	10.00	\$268.45	Replace	an
6012141	VE	ELU-00312	HEADLAMP, BEAM: DIPPED, FOR VOLVO B9TL BUS	1.00	\$445.00	10.00	\$400.50	Replace	dis
6012121	Body	A12-02429	BATTERY ACCESS DOOR	1.00	\$1,359.65	10.00	\$1,223.69	Replace	bt
Total					\$6,712.19		\$2,988.22		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3320.24
10% - 2988.216
US 20% 2390.57
1060
432
3882.57
≈ US\$3900 03 days