

ASS. REC. BY:

REF: ASH / 23000923/KnKenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 880k

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 06 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMD 96314Yr Regn: 09, 18Type: ☒ M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda

c.c.

1496Colour: M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading: 64447

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RUI1304325Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mm

Rear

R/Bal. 3 mmL/Bal. 4 mmL/Bal. 3 mmD.O.A. 27/1/23D.O.I. 31/1/2023

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation

S - RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

ump Sum / I.B.I. (\$

TOTAL

**SERVE YOU MOTOR SERVICE PTE LTD**  
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2  
 #01-265 SINGAPORE 569536  
 TEL. NO.: 6481 0555/ FAX NO. 6483 1654  
 E-MAIL: elainesyms@gmail.com

*Not Authorised*  
*11 Rps @*  
*Returning After Paint*  
*Today*

|                                   |                 |                                  |                             |
|-----------------------------------|-----------------|----------------------------------|-----------------------------|
| <b>Vehicle Number:</b>            | <b>SMD9631U</b> | <b>Vehicle Made &amp; Model:</b> | <b>Honda Vezel 1.5X CVT</b> |
| <b>Accident date : 27-01-2023</b> |                 | <b>NO : 230122</b>               |                             |

| No        | Qty | List Items                          | Amount SGD  |        |
|-----------|-----|-------------------------------------|-------------|--------|
| 1         | 1   | Tailgate                            | \$1,150.00  | —      |
| 2         | 1   | Tailgate Windscreen Moulding        | \$285.00    | —      |
| 3         | 1   | Tailgate Outer Garnish              | \$330.00    | X      |
| 4         | 1   | Tailgate Outer Garnish Clip Set     | \$40.00     | 1      |
| 5         | 2   | Tailgate Lamp                       | \$730.00    | 1/1 cm |
| 6         | 1   | Tailgate Lamp Clip Set              | \$40.00     | X      |
| 7         | 1   | Tailgate Lock                       | \$188.00    | —      |
| 8         | 1   | Tailgate 'H' Logo                   | \$32.00     | X      |
| 9         | 1   | Tailgate 'Vezel' Emblem             | \$63.00     | —      |
| 10        | 1   | Tailgate Inner Trimboard            | \$220.00    | X      |
| 11        | 1   | Tailgate Weatherstrip               | \$118.00    | —      |
| 12        | 2   | Tailgate Stopper                    | \$24.00     | X      |
| 13        | 2   | Taillamp                            | \$1,040.00  | 1/1 cm |
| 14        | 2   | Taillamp Panel                      | \$480.00    | X      |
| 15        | 1   | Rear Bumper                         | \$750.00    | —      |
| 16        | 2   | Rear Bumper Side Retainer           | \$75.00     | X      |
| 17        | 2   | Rear Bumper Side                    | \$450.00    | X      |
| 18        | 2   | Rear Bumper Reflector               | \$180.00    | X      |
| 19        | 2   | Fender Wheel Arch Garnish           | \$280.00    | 1/1 cm |
| 20        | 1   | Rear Bumper Under Cover             | \$240.00    | X      |
| 21        | 1   | Rear End Panel                      | \$550.00    | —      |
| 22        | 1   | Rear End Panel Top Garnish          | \$168.00    | X      |
| 23        | 1   | Buzzer Sensor                       | \$120.00    | X      |
| 24        | 1   | Antenna Sensor                      | \$110.00    | X      |
| 25        | 1   | Fender out trm (portector)          | \$626.60    | X      |
| 26        |     | Rear rh muffler                     | \$88.90     | X      |
| 27        | 2   | Fender Inner Trimboard              | \$750.00    | X      |
| 28        | 2   | Fender Inner Shield                 | \$377.60    | X      |
| 29        | 1   | Floor Panel                         | \$668.00    | X      |
| 30        | 1   | Floor Panel Compartment Sponge Tray | \$485.00    | X      |
| 31        | 1   | Floor Panel Top Board               | \$240.00    | X      |
| Sub-total |     |                                     | \$10,899.10 |        |
| Less 20%  |     |                                     | \$ 2,179.82 |        |
| Total     |     |                                     | \$ 8,719.28 |        |

**SERVE YOU MOTOR SERVICE PTE LTD**  
**BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2**  
**#01-265 SINGAPORE 569536**  
**TEL. NO.: 6481 0555/ FAX NO. 6483 1654**  
**E-MAIL: elainesyms@gmail.com**

|                        |                   |                                  |                             |
|------------------------|-------------------|----------------------------------|-----------------------------|
| <b>Vehicle Number:</b> | <b>SMD9631U</b>   | <b>Vehicle Made &amp; Model:</b> | <b>Honda Vezel 1.5X CVT</b> |
| <b>Accident date :</b> | <b>27-01-2023</b> | <b>NO :</b>                      | <b>230123</b>               |

**Special Nett Items**

- 1 Windscreen Sealant
- 2 Windscreen Seal
- 3 Taillamp Seal Set
- 4 Tailgate Lamp Seal Set
- 5 Bumper Clip Set
- 6 Bumper Under Cover Clip Set
- 7 End Panel Sealant
- 8 Fender Inner Trim Board Clip Set
- 9 Fender Arch Garnish Clip Set
- 10 Reverse Sensor Set
- 11 Reverse Camera Set
- 12 Rear Number Plate With Holder

|                           |          |                   |
|---------------------------|----------|-------------------|
| mm                        | \$80.00  | 40sn              |
| na                        | \$50.00  | 30sn              |
| na                        | \$30.00  | X                 |
| na                        | \$30.00  | X                 |
| na                        | \$50.00  | ✓                 |
| na                        | \$60.00  | X                 |
| na                        | \$80.00  | 30sn              |
| na                        | \$80.00  | X                 |
| na                        | \$80.00  | LT                |
| Ref                       | \$280.00 | 200sn             |
| that                      | \$380.00 | 250               |
| na                        | \$60.00  | X                 |
| <b>Total Special Nett</b> |          | <b>\$1,260.00</b> |

**Labour Charges**

- 1 To Check Wiring And Lighting
- 2 To Conduct Water Seepage Test
- 3 To Remove And Replace Reverse Sensor
- 4 To Remove And Replace Reverse Camera
- 5 To Transfer Tailgate Mechanism From Old to New Parts
- 6 To Apply Anti-Rust Proofing On Affected Areas
- 7 To Replace And Refix Rear Windscreen
- 8 To Remove, Replace & Refix Inner Trim, Garnish, Rear Set And Upholstery
- 9 To Perform Diagnostic Check For Fault Code And Reset Factory Settings
- 10 To Panel Beat And Replace Damaged Parts On Affected Areas
- 11 To Putty And Spray Painting On Affected Areas

|                     |           |                    |
|---------------------|-----------|--------------------|
| \$                  | 80.00     | 20l                |
| \$                  | 60.00     | 20l                |
| \$                  | 80.00     | 50l                |
| \$                  | 80.00     | 50l                |
| \$                  | 100.00    | 60l                |
| \$                  | 100.00    |                    |
| \$                  | 150.00    | 120l               |
| \$                  | 150.00    | 60l                |
| na                  | \$ 150.00 | X                  |
| \$                  | 1,500.00  | 800l               |
| \$                  | 1,500.00  | 800l               |
| <b>Total Labour</b> |           | <b>\$ 3,950.00</b> |

**ESTIMATE PARTS AND LABOURS GRAND TOTAL**

**\$ 13,929.28**

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: