

JHL SIN HENG LONG
MOTOR

Kennerth (Lkk) Not Auth

*Not Authorized
L1 Rep & 480dp
Inventory After Paint
Today*

SERVE YOU MOTOR SERVICE PTE LTD
BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
#01-265 SINGAPORE 569536
TEL. NO.: 6481 0555/ FAX NO. 6483 1654
E-MAIL: elainesyms@gmail.com

Vehicle Number: **SMD9631U** Vehicle Made & Model: **Honda Vezel 1.5X CVT**
Accident date : 27-01-2023 NO : 230122

No	Qty	List Items	Amount SGD
1	1	Tailgate <i>1068-10</i>	<i>Bt</i> \$1,150.00 ✓
2	1	Tailgate Windscreen Moulding <i>112</i>	<i>nn</i> \$285.00 ✓
3	1	Tailgate Outer Garnish	<i>nn</i> \$330.00 X
4	1	Tailgate Outer Garnish Clip Set	<i>nn</i> \$40.00 ✓
5	2	Tailgate Lamp	<i>ols cm</i> \$730.00 ✓
6	1	Tailgate Lamp Clip Set	<i>nn</i> \$40.00 X
7	1	Tailgate Lock	<i>nn</i> \$188.00 ✓
8	1	Tailgate 'H' Logo	<i>nn</i> \$32.00 X
9	1	Tailgate 'Vezel' Emblem	<i>nn</i> \$63.00 ✓
10	1	Tailgate Inner Trimboard	<i>nn</i> \$220.00 X
11	1	Tailgate Weatherstrip	<i>nn</i> \$118.00 ✓
12	2	Tailgate Stopper	<i>nn</i> \$24.00 X
13	2	Taillamp	<i>ols cm</i> \$1,040.00 ✓
14	2	Taillamp Panel	<i>nn</i> \$480.00 X
15	1	Rear Bumper	<i>Bt</i> \$750.00 ✓
16	2	Rear Bumper Side Retainer	<i>nn ottd</i> \$75.00 X
17	2	Rear Bumper Side	<i>nn</i> \$450.00 X
18	2	Rear Bumper Reflector	<i>nn</i> \$180.00 X
19	2	Fender Wheel Arch Garnish	<i>ols Bu</i> \$280.00 ✓
20	1	Rear Bumper Under Cover	<i>cm</i> \$240.00 X
21	1	Rear End Panel	<i>Bt</i> \$550.00 ✓
22	1	Rear End Panel Top Garnish	<i>nn</i> \$168.00 X
23	1	Buzzer Sensor	<i>nn</i> \$120.00 X
24	1	Antenna Sensor	<i>nn</i> \$110.00 X
25	1	Fender out trm (portector)	<i>nn</i> \$626.60 X
26	1	Rear rh muffler	<i>nn</i> \$88.90 X
27	2	Fender Inner Trimboard	<i>nn</i> \$750.00 X
28	2	Fender Inner Shield	<i>nn</i> \$377.60 X
29	1	Floor Panel	<i>nn</i> \$668.00 X
30	1	Floor Panel Compartment Sponge Tray	<i>nn</i> \$485.00 X
31	1	Floor Panel Top Board	<i>nn</i> \$240.00 X
Sub-total			\$10,899.10
Less 20%			\$ 2,179.82
Total			\$ 8,719.28

823/161

SERVE YOU MOTOR SERVICE PTE LTD
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265 SINGAPORE 569536
 TEL. NO.: 6481 0555/ FAX NO. 6483 1654
 E-MAIL: elainesyms@gmail.com

Vehicle Number: SMD9631U **Vehicle Made & Model:** Honda Vezel 1.5X CVT
Accident date : 27-01-2023 **NO :** 230123

Special Nett Items

- 1 Windscreen Sealant
- 2 Windscreen Seal
- 3 Taillamp Seal Set
- 4 Tailgate Lamp Seal Set
- 5 Bumper Clip Set
- 6 Bumper Under Cover Clip Set
- 7 End Panel Sealant
- 8 Fender Inner Trim Board Clip Set
- 9 Fender Arch Garnish Clip Set
- 10 Reverse Sensor Set
- 11 Reverse Camera Set
- 12 Rear Number Plate With Holder

405m
 m \$80.00
 na \$50.00 301m
 na \$30.00 X
 na \$30.00 X
 na \$50.00 ✓
 na \$60.00 X
 na \$80.00 301m
 na \$80.00 X
 na \$80.00 405m
 na \$280.00 2005m
 na \$380.00 2501
 na \$60.00 X

Total Special Nett \$1,260.00

Labour Charges

- 1 To Check Wiring And Lighting
- 2 To Conduct Water Seepage Test
- 3 To Remove And Replace Reverse Sensor
- 4 To Remove And Replace Reverse Camera
- 5 To Transfer Tailgate Mechanism From Old to New Parts
- 6 To Apply Anti-Rust Proofing On Affected Areas
- 7 To Replace And Refix Rear Windscreen
- 8 To Remove, Replace & Refix Inner Trim, Garnish, Rear Set And Upholstery
- 9 To Perform Diagnostic Check For Fault Code And Reset Factory Settings
- 10 To Panel Beat And Replace Damaged Parts On Affected Areas
- 11 To Putty And Spray Painting On Affected Areas

201
 \$ 80.00
 \$ 60.00 201
 \$ 80.00 501
 \$ 80.00 501
 \$ 100.00 601
 \$ 100.00
 \$ 150.00 1201
 \$ 150.00 601
 na \$ 150.00 X
 \$ 1,500.00 8001
 \$ 1,500.00 9001

Total Labour \$ 3,950.00

ESTIMATE PARTS AND LABOURS GRAND TOTAL

\$ 13,929.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: