

SERVE YOU MOTOR SERVICE PTE LTD
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265 SINGAPORE 569536
 TEL. NO.: 6481 0555/ FAX NO. 6483 1654
 E-MAIL: elainesyms@gmail.com

Not Authorised
11 Rps @
Returning After Paint
Today

Vehicle Number:	SMD9631U	Vehicle Made & Model:	Honda Vezel 1.5X CVT
Accident date : 27-01-2023		NO : 230122	

No	Qty	List Items	Amount SGD	
1	1	Tailgate	\$1,150.00	—
2	1	Tailgate Windscreen Moulding	\$285.00	—
3	1	Tailgate Outer Garnish	\$330.00	X
4	1	Tailgate Outer Garnish Clip Set	\$40.00	1
5	2	Tailgate Lamp	\$730.00	1/1 cm
6	1	Tailgate Lamp Clip Set	\$40.00	X
7	1	Tailgate Lock	\$188.00	—
8	1	Tailgate 'H' Logo	\$32.00	X
9	1	Tailgate 'Vezel' Emblem	\$63.00	—
10	1	Tailgate Inner Trimboard	\$220.00	X
11	1	Tailgate Weatherstrip	\$118.00	—
12	2	Tailgate Stopper	\$24.00	X
13	2	Taillamp	\$1,040.00	1/1 cm
14	2	Taillamp Panel	\$480.00	X
15	1	Rear Bumper	\$750.00	—
16	2	Rear Bumper Side Retainer	\$75.00	X
17	2	Rear Bumper Side	\$450.00	X
18	2	Rear Bumper Reflector	\$180.00	X
19	2	Fender Wheel Arch Garnish	\$280.00	1/1 cm
20	1	Rear Bumper Under Cover	\$240.00	X
21	1	Rear End Panel	\$550.00	—
22	1	Rear End Panel Top Garnish	\$168.00	X
23	1	Buzzer Sensor	\$120.00	X
24	1	Antenna Sensor	\$110.00	X
25	1	Fender out trm (portector)	\$626.60	X
26		Rear rh muffler	\$88.90	X
27	2	Fender Inner Trimboard	\$750.00	X
28	2	Fender Inner Shield	\$377.60	X
29	1	Floor Panel	\$668.00	X
30	1	Floor Panel Compartment Sponge Tray	\$485.00	X
31	1	Floor Panel Top Board	\$240.00	X
Sub-total			\$10,899.10	
Less 20%			\$ 2,179.82	
Total			\$ 8,719.28	

SERVE YOU MOTOR SERVICE PTE LTD
BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
#01-265 SINGAPORE 569536
TEL. NO.: 6481 0555/ FAX NO. 6483 1654
E-MAIL: elainesyms@gmail.com

Vehicle Number: SMD9631U	Vehicle Made & Model: Honda Vezel 1.5X CVT
Accident date : 27-01-2023	NO : 230123

Special Nett Items

- 1 Windscreen Sealant
- 2 Windscreen Seal
- 3 Taillamp Seal Set
- 4 Tailgate Lamp Seal Set
- 5 Bumper Clip Set
- 6 Bumper Under Cover Clip Set
- 7 End Panel Sealant
- 8 Fender Inner Trim Board Clip Set
- 9 Fender Arch Garnish Clip Set
- 10 Reverse Sensor Set
- 11 Reverse Camera Set
- 12 Rear Number Plate With Holder

mm	\$80.00	40sn
na	\$50.00	30sn
na	\$30.00	X
na	\$30.00	X
na	\$50.00	✓
na	\$60.00	X
na	\$80.00	30sn
na	\$80.00	X
na	\$80.00	LT
Ad	\$280.00	200sn
that	\$380.00	250
na	\$60.00	X
Total Special Nett		\$1,260.00

Labour Charges

- 1 To Check Wiring And Lighting
- 2 To Conduct Water Seepage Test
- 3 To Remove And Replace Reverse Sensor
- 4 To Remove And Replace Reverse Camera
- 5 To Transfer Tailgate Mechanism From Old to New Parts
- 6 To Apply Anti-Rust Proofing On Affected Areas
- 7 To Replace And Refix Rear Windscreen
- 8 To Remove, Replace & Refix Inner Trim, Garnish, Rear Set And Upholstery
- 9 To Perform Diagnostic Check For Fault Code And Reset Factory Settings
- 10 To Panel Beat And Replace Damaged Parts On Affected Areas
- 11 To Putty And Spray Painting On Affected Areas

\$	80.00	20l
\$	60.00	20l
\$	80.00	50l
\$	80.00	50l
\$	100.00	60l
\$	100.00	
\$	150.00	120l
\$	150.00	60l
na	\$	150.00 X
\$	1,500.00	800l
\$	1,500.00	800l
Total Labour		\$ 3,950.00

ESTIMATE PARTS AND LABOURS GRAND TOTAL

\$ 13,929.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: