

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2301-042

DATE : 25-Jan-2023

POLICY NO. : AUTO&GEN P10708655R00

VEHICLE REG. NO. : SMY5055Z

VEHICLE MAKE : HYUNDAI CN7 AVANTE 1.6 DOHC CVT S

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 580.00	\$ 580.00
2	Rear Bumper Lower	1	\$ 420.00	\$ 420.00
3	Rear Bumper Clips	10	\$ 3.00	\$ 30.00
4	Rear Bumper Lower Reflector RH	1	\$ 60.00	\$ 60.00
5	Rear Bumper Lower Reflector LH	1	\$ 60.00	\$ 60.00
6	Rear Reinforcement	1	\$ 320.00	\$ 320.00
7	Rear Bumper Retainer RH	1	\$ 40.00	\$ 40.00
8	Rear Bumper Retainer LH	1	\$ 40.00	\$ 40.00
9	Rear Bumper Under Cover LH	1	\$ 40.00	\$ 40.00
10	Rear Insert Air Grille Vent LH	1	\$ 40.00	\$ 40.00
11	Rear Fender Rear Shield LH	1	\$ 80.00	\$ 80.00
12	Rear Avante Emblem	1	\$ 40.00	\$ 40.00
13	Rear Bootlid	1	\$ 2,100.00	\$ 2,100.00
14	Rear Bootlid Inner Trim	1	\$ 150.00	\$ 150.00
15	Rear Bootlid Hinge RH	1	\$ 150.00	\$ 150.00
16	Rear Bootlid Hinge LH	1	\$ 150.00	\$ 150.00
17	Rear Bootlid Lower Latch	1	\$ 30.00	\$ 30.00
18	Rear Bootlid Lock	1	\$ 120.00	\$ 120.00
19	Rear Bootlid Rubber Seal	1	\$ 120.00	\$ 120.00
20	End Panel	1	\$ 600.00	\$ 600.00
21	End Panel Garnish	1	\$ 80.00	\$ 80.00
22	Rear Mat Luggage Cover	1	\$ 220.00	\$ 220.00
23	Rear Floor Panel	1	\$ 280.00	\$ 280.00
24	Tail lamp RH	1	\$ 680.00	\$ 680.00
25	Tail lamp LH	1	\$ 680.00	\$ 680.00
26	Tail lamp Special Clip	2	\$ 5.00	\$ 10.00
27	Bootlip lamp Center	1	\$ 1,100.00	\$ 1,100.00
28	Rear License Lamp	2	\$ 40.00	\$ 80.00
29	Reverse Sensor	4	\$ 180.00	\$ 720.00
30	Reverse Sensor Harness Cable	1	\$ 250.00	\$ 250.00
31	Rear Corner Radar LH	1	\$ 1,200.00	\$ 1,200.00
Total Spare Parts				\$ 10,470.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2301-042

DATE : 25-Jan-2023

POLICY NO. : AUTO&GEN P10708655R00

VEHICLE REG. NO. : SMY5055Z

VEHICLE MAKE : HYUNDAI CN7 AVANTE 1.6 DOHC CVT S

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPECIAL NETT</u>			
32	Rear Number Plate with Frame	1	\$ 40.00	\$ 40.00
Total Special Nett				\$ 40.00
	<u>LABOUR</u>			
33	Spray Painting Whole Rear	1	\$ 800.00	\$ 800.00
34	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,000.00	\$ 1,000.00
35	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
36	Reset and Program Blindspot Radar Sensor	1	\$ 280.00	\$ 280.00
37	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
38	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,290.00
Amount Before Excess				\$ 12,800.00
Add GST @ 7%				896.00
Total Amount Payable				\$ 13,696.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.