



3A Automobile Pte Ltd

Office Address : No 120 Lower Delta Road #02-15 Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

To : Claims Department

Vehicles Number: SLK 3940 S

Make and Model: BMW X1

Date Of Accident: 20/Jan/2023

Time Accident: 1750HRS

Tel : 64307900

Fax : 63381500/1504

Attn: Motor Claims Department

Unit	List Items	Unit Price	Prices
1 pc	Rear Bumper Assy <i>SLK</i>	\$900.00	\$900.00
			\$ 900.00
		Less: 5%	(\$45.00)

900
58
855

Unit	Nett Items	Unit Price	Prices
20 pcs	Bumper Clips	\$5.00	\$100.00
		S/Total	\$ 955.00

Xnn

Labour Charges

	To Remove & Replace the Damaged Parts as Listed Above, including Reinstallments of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts	200	\$500.00
	To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint on Rear Bumper with Oven Spray Booth Facilities	200	\$400.00
	To Transfer Tailgate Lock Mechanism	X	\$100.00

450

250

Total \$ 1,955.00

Yours faithfully,

3A Automobile Pte Ltd

Person to contact : Angie Yong

Phone No.: 9001 6128

855

450

1305

206

1044

45- \$1,050 / 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Raghu

Hy 90010068

2 days

45

31/01/23 @ 1K85

Rag after repair