



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23000937/Rvp3m4

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 24/02/2023

ATTN: YO YO TIAN TIAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 2766T	Veh. Inspected	SHC 7238A
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1207369-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	31/01/2023

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40 1.7 CRDI	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU092563	Colour	YELLOW
Odometer	567757 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	APLUS	6 mm
L/H Front Tyre	205/60 R16	APLUS	6 mm
R/H Rear Tyre	205/60 R16	APLUS	6 mm
L/H Rear Tyre	205/60 R16	APLUS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/01/2023	Inspect Date / Time	31/01/2023 (02:20 PM)
Survey held at	31 CORPORATION ROAD SINGAPORE 649825		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**