

五

Kenneth

On the

N/S	O/S

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Reg = 2/2/2015

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SKR3625C
Chassis No : JHMRC1880EC204309
Model : ODYSSEY 2.4 EX-S 14YM(EURO 4)
Owner's Name : KOH HWEE KUI
Ins Policy No :
Date of Accident : 23/1/2023

Document No. : SQT23000207
Date : 25. Jan 2023
Customer No. : WZ1007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W71001844
Date | Time : 25. Jan 2023 4:16:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: KOH HWEE KUI OWNER INSURER: TOKIO MARINE ACC DATE: 23/01/2023 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INT'L INSURANCE TP VEH: SNC7702E						
68100-T6A-Q10ZZ	TAILGATE COMP	1	1146.20	25	859.65	68.77	928.42 ✓
68210-T6A-003ZZ	HINGE COMPTAILGATE	2	38.20	25	57.30	4.58	61.88 X
74440-T6A-003	WEATHERSTRIPTAILGATE	1	125.70	25	94.27	7.54	101.81 ✓
74800-TF0-J01	LOCKTAILGATE	1	200.40	25	150.30	12.02	162.32 X
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	246.70	25	185.02	14.80	199.82 ✓
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	187.90	25	140.92	11.27	152.19 ✓
75701-T6A-000	EMBLEMH	1	28.20	25	21.15	1.69	22.84 ✓
91512-SR3-004	CLIP TUBULAR	2	2.40	25	3.60	0.29	3.89 ✓
84431-T6A-J01ZB	LINING ASSYTAILGATE LOWER	1	220.80	25	165.60	13.25	178.85 ✓
04715-T6A-000ZZ	FACERR.BUMPER	1	592.70	25	444.52	35.56	480.08 ✓
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	20.40	25	15.30	1.22	16.52 ✓
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	20.40	25	15.30	1.22	16.52 ✓
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.38	18.63 ✓
71502-T6A-003ZE	FACER.RR.BUMPER GARNISH	1	84.70	25	63.52	5.08	68.60 ✓
71507-T6A-003ZE	FACEL.RR.BUMPER GARNISH	1	84.70	25	63.52	5.08	68.60 X
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	48.50	25	36.37	2.91	39.28 7
33555-SLJ-013	REFLECTOR ASSYL.RR.	1	48.50	25	36.37	2.91	39.28 X
66100-T6A-310ZZ	PANEL COMP,RR.	1	493.20	25	369.90	29.59	399.49 ✓
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	361.70	25	271.27	21.70	292.97 X

NOT AUTHORIZED
Surveying By Repair
9 days

Printed on 26/1/2023 2:04:26 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SKR3625C

Chassis No : JHMRC1880EC204309

Model : ODYSSEY 2.4 EX-S 14YM(EURO 4)

Owner's Name : KOH HWEE KUI

Ins Policy No. :

Date of Accident : 23/1/2023

Document No. : SQT23000207

Date : 25. Jan 2023

Customer No. : WZ1007

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : K24W71001844

Date | Time : 25. Jan 2023 4:16:00 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
84640-T6A-003ZB	LINING ASSYRR.PANEL	1	110.90	25	83.17	6.65	89.82
84643-T6A-Q01ZB	COMP LIDTOOL	1	65.70	25	49.27	3.94	53.21
33500-T6A-003	TAILLIGHT ASSYR.	1	897.20	25	672.90	53.83	726.73
33550-T6A-003	TAILLIGHT ASSYL.	1	897.20	25	672.90	53.83	726.73
34150-T6A-003	LIGHT ASSY,R.LID	1	413.40	25	310.05	24.80	334.85
34155-T6A-003	LIGHT ASSYL.LID	1	413.40	25	310.05	24.80	334.85
38387-T6A-J01	ANTENNA ASSY,SMAR	1	81.70	25	61.27	4.90	66.17
74940-TR0-003	BUZZER ASSYSMART	1	64.30	25	48.22	3.86	52.08
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.60	48.60
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	25.60	345.60
18307-T6A-J02	SILENCER COMPEXHAUST	1	695.20	25	521.40	41.71	563.11
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	25	28.80	2.30	31.10
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	25	12.60	1.01	13.61
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.90	25	2.92	0.23	3.15
73226-SZW-000	DAMPERSTD 5X5	2	9.10	25	13.65	1.09	14.74
76711-T6A-003	CAPPIVOT	1	5.20	25	3.90	0.31	4.21
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.80	64.80
Sum Item					6254.37	500.30	6,754.67

BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00	✓	650.00	52.00	702.00
BOSUN	SUNDRIES	1	100.00	301	100.00	8.00	108.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00	✓	160.00	12.80	172.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00	✓	140.00	11.20	151.20
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	340.00	✓	340.00	27.20	367.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	340.00	✓	340.00	27.20	367.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	380.00	✓	380.00	30.40	410.40

Printed on 26/1/2023 2:04:26 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SKR3625C
Chassis No : JHMRC1880EC204309
Model : ODYSSEY 2.4 EX-S 14YM(EURO 4)
Owner's Name : KOH HWEE KUI
Ins Policy No. :
Date of Accident : 23/1/2023

Document No. : SQT23000207
Date : 25. Jan 2023
Customer No. : WZ1007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W71001844
Date | Time : 25. Jan 2023 4:16:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	540.00	✓	540.00	43.20	583.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	100%	250.00	20.00	270.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00	80%	100.00	8.00	108.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00	80%	100.00	8.00	108.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	100.00	X	100.00	8.00	108.00
BKRP02B	CUT & RENEW RR FLOOR PANEL. STRAIGHTEN FENDERS ALIG	1	4500.00	3250%	4500.00	360.00	4860.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00	3120%	4000.00	320.00	4320.00
Sum Labor					11700.00	936.00	12,636.00

Survey By

Date & Time

Excess

Status

Signature

Total Amount 17,954.37 1,436.30 19,390.67

Total (Inclusive of GST) 19,390.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 26/1/2023 2:04:26 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

SK0L231P0005 / KAH MOTOR CO SDN BHD [729905]
ENTRY DATE & TIME: 25/01/2023 16:01 (SGT)
SUBMITTED BY: LAI SWEE KAM ANIKKA
VERSION: 1 (25/01/2023 16:01 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/01/2023 16:01 (SGT)
Reported by	Both
Date of Accident	23/01/2023 13:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE (CITY) B4 AMK AVE 5 EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR3625C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	KOH HWEE KUI
NRIC No	SXXXX011E
Email Address	nge65@yahoo.com.sg
Mobile Phone No	(Phone) +65-97651287
Alternative Phone No	+65-97960098

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Odyssey
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2400

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number	MW001065

DRIVER

Name of Driver	KOH HWEE KUI
NRIC No	SXXXX011E
Date Of Birth	02/05/1965
Occupation	Indoor

483.90
155.60

Rear end panel
Rear end panel garnish

