

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SKR3625C
Chassis No : JHMRC1880EC204309
Model : ODYSSEY 2.4 EX-S 14YM(EURO 4)
Owner's Name : KOH HWEE KUI
Ins Policy No. :
Date of Accident : 23/1/2023

Document No. : SQT23000207 Page 2
Date : 25. Jan 2023
Customer No. : WZ1007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W71001844
Date | Time : 25. Jan 2023 4:16:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
84640-T6A-003ZB	LINING ASSYRR.PANEL	1	110.90	25	83.17	6.65	89.82
84643-T6A-Q01ZB	COMP LIDTOOL	1	65.70	25	49.27	3.94	53.21
33500-T6A-003	TAILLIGHT ASSYR.	1	897.20	25	672.90	53.83	726.73
33550-T6A-003	TAILLIGHT ASSYL.	1	897.20	25	672.90	53.83	726.73
34150-T6A-003	LIGHT ASSY,R.LID	1	413.40	25	310.05	24.80	334.85
34155-T6A-003	LIGHT ASSYL.LID	1	413.40	25	310.05	24.80	334.85
38387-T6A-J01	ANTENNA ASSY,SMAR	1	81.70	25	61.27	4.90	66.17
74940-TR0-003	BUZZER ASSYSMART	1	64.30	25	48.22	3.86	52.08
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.60	48.60
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	25.60	345.60
18307-T6A-J02	SILENCER COMPEXHAUST	1	695.20	25	521.40	41.71	563.11
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	25	28.80	2.30	31.10
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	25	12.60	1.01	13.61
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.90	25	2.92	0.23	3.15
73226-SZW-000	DAMPERSTD 5X5	2	9.10	25	13.65	1.09	14.74
76711-T6A-003	CAPPIVOT	1	5.20	25	3.90	0.31	4.21
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.80	64.80
Sum Item					6254.37	500.30	6,754.67
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	52.00	702.00
BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00		160.00	12.80	172.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00		140.00	11.20	151.20
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	340.00		340.00	27.20	367.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	340.00		340.00	27.20	367.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	380.00		380.00	30.40	410.40

Printed on 26/1/2023 2:04:26 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SKR3625C

Chassis No : JHMRC1880EC204309

Model : ODYSSEY 2.4 EX-S 14YM(EURO 4)

Owner's Name : KOH HWEE KUI

Ins Policy No. :

Date of Accident : 23/1/2023

Document No. : SQT23000207

Date : 25. Jan 2023

Customer No. : WZ1007

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : K24W71001844

Date | Time : 25. Jan 2023 4:16:00 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	540.00	✓	540.00	43.20	583.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	100%	250.00	20.00	270.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00	80%	100.00	8.00	108.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00	80%	100.00	8.00	108.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	100.00	✓ 80.00	100.00	8.00	108.00
BKRP02B	CUT & RENEW RR FLOOR PANEL. STRAIGHTEN FENDERS ALIG	1	4500.00	3900%	4500.00	360.00	4860.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00	3120%	4000.00	320.00	4320.00
Sum Labor					11700.00	936.00	12,636.00

Survey By

Date & Time

Excess

Status

Signature

Total Amount 17,954.37 1,436.30 19,390.67

Total (Inclusive of GST) 19,390.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 26/1/2023 2:04:26 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer:	CU0050391 / INDIA	Document No:	SVO23003651
Chassis No:	JHMRC1880EC204309	Printed By:	ANIKKALAI
License No:	SKR3625C	Order Date:	27. January 2023
Mileage:	87227	Order Time:	9:35:41 AM
Engine No:	K24W71001844	Service Advisor:	ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	8% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER: KOH HWEE KUI							
	OWNER INSURER: TOKIO MARINE							
	ACC DATE: 23/01/2023							
	SURVEYED BY: KENNETH / LKK							
	DATE: 26/01/2023							
	REF NO:							
	TP INSURER: INDIA INT'L INSURANCE							
	TP VEH: SNC7702E							
	SUPPLEMENTARY PART							
84615-T6A-J13ZA	LINING COMP,R.RR.SIDE	1	672.80	25	504.60	40.37	544.97	
74827-T0A-A00	STOPPERTAILGATE	1	3.80	25	2.85	0.23	3.08	
72841-SH3-315	OILSHEET	1	43.50	25	32.62	2.61	35.23	
84441-T6A-J01ZB	POCKETTAILGATE LINING PULL	1	11.50	25	8.62	0.69	9.31	