



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SKR3625C
Chassis No : JHMRC1880EC204309
Model : ODYSSEY 2.4 EX-S 14YM(EURO 4)
Owner's Name : KOH HWEE KUI
Ins Policy No. :
Date of Accident : 23/1/2023

Document No. : SQT23000207 **Page** 1
Date : 25. Jan 2023
Customer No. : WZI007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W71001844
Date | Time : 25. Jan 2023 4:16:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: KOH HWEE KUI OWNER INSURER: TOKIO MARINE ACC DATE: 23/01/2023 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INT'L INSURANCE TP VEH: SNC7702E						
68100-T6A-Q10ZZ	TAILGATE COMP	1	1146.20	25	859.65	68.77	928.42
68210-T6A-003ZZ	HINGE COMPTAILGATE	2	38.20	25	57.30	4.58	61.88
74440-T6A-003	WEATHERSTRIPTAILGATE	1	125.70	25	94.27	7.54	101.81
74800-TF0-J01	LOCKTAILGATE	1	200.40	25	150.30	12.02	162.32
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	246.70	25	185.02	14.80	199.82
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	187.90	25	140.92	11.27	152.19
75701-T6A-000	EMBLEMH	1	28.20	25	21.15	1.69	22.84
91512-SR3-004	CLIP TUBULAR	2	2.40	25	3.60	0.29	3.89
84431-T6A-J01ZB	LINING ASSYTAILGATE LOWER	1	220.80	25	165.60	13.25	178.85
04715-T6A-000ZZ	FACERR.BUMPER	1	592.70	25	444.52	35.56	480.08
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	20.40	25	15.30	1.22	16.52
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	20.40	25	15.30	1.22	16.52
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.38	18.63
71502-T6A-003ZE	FACER.RR.BUMPER GARNISH	1	84.70	25	63.52	5.08	68.60
71507-T6A-003ZE	FACEL.RR.BUMPER GARNISH	1	84.70	25	63.52	5.08	68.60
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	48.50	25	36.37	2.91	39.28
33555-SLJ-013	REFLECTOR ASSYL.RR.	1	48.50	25	36.37	2.91	39.28
66100-T6A-310ZZ	PANEL COMP,RR.	1	493.20	25	369.90	29.59	399.49
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	361.70	25	271.27	21.70	292.97

Printed on 25/1/2023 5:10:11 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SKR3625C
Chassis No : JHMRC1880EC204309
Model : ODYSSEY 2.4 EX-S 14YM(EURO 4)
Owner's Name : KOH HWEE KUI
Ins Policy No. :
Date of Accident : 23/1/2023

Document No. : SQT23000207 **Page** 2
Date : 25. Jan 2023
Customer No. : WZI007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W71001844
Date | Time : 25. Jan 2023 4:16:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
84640-T6A-003ZB	LINING ASSYRR.PANEL	1	110.90	25	83.17	6.65	89.82
84643-T6A-Q01ZB	COMP LIDTOOL	1	65.70	25	49.27	3.94	53.21
33500-T6A-003	TAILLIGHT ASSYR.	1	897.20	25	672.90	53.83	726.73
33550-T6A-003	TAILLIGHT ASSYL.	1	897.20	25	672.90	53.83	726.73
34150-T6A-003	LIGHT ASSY,R.LID	1	413.40	25	310.05	24.80	334.85
34155-T6A-003	LIGHT ASSYL.LID	1	413.40	25	310.05	24.80	334.85
38387-T6A-J01	ANTENNA ASSY,SMAR	1	81.70	25	61.27	4.90	66.17
74940-TR0-003	BUZZER ASSYSMART	1	64.30	25	48.22	3.86	52.08
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.60	48.60
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	25.60	345.60
18307-T6A-J02	SILENCER COMPEXHAUST	1	695.20	25	521.40	41.71	563.11
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	25	28.80	2.30	31.10
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	25	12.60	1.01	13.61
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.90	25	2.92	0.23	3.15
73226-SZW-000	DAMPERSTD 5X5	2	9.10	25	13.65	1.09	14.74
76711-T6A-003	CAPPIVOT	1	5.20	25	3.90	0.31	4.21
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.80	64.80
Sum Item					6254.37	500.30	6,754.67
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	52.00	702.00
BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00		160.00	12.80	172.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00		140.00	11.20	151.20
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	340.00		340.00	27.20	367.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	340.00		340.00	27.20	367.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	380.00		380.00	30.40	410.40

Printed on 25/1/2023 5:10:11 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT23000207	Page	3
Registration No	: SKR3625C	Date	: 25. Jan 2023		
Chassis No	: JHMRC1880EC204309	Customer No.	: WZI007		
Model	: ODYSSEY 2.4 EX-S 14YM(EURO 4)	Svc Advisor	: ANIKKA LAI SWEE KAM		
Owner's Name	: KOH HWEE KUI	Engine No	: K24W71001844		
Ins Policy No.	:	Date Time	: 25. Jan 2023 4:16:00 PM		
Date of Accident	: 23/1/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	540.00		540.00	43.20	583.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	20.00	270.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00		100.00	8.00	108.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00		100.00	8.00	108.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	100.00		100.00	8.00	108.00
BKRP02B	CUT & RENEW RR FLOOR PANEL. STRAIGHTEN FENDERS ALIG	1	4500.00		4500.00	360.00	4860.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00		4000.00	320.00	4320.00
Sum Labor					11700.00	936.00	12,636.00

Survey By

Date & Time

Excess

Status

Signature

Total Amount 17,954.37 1,436.30 19,390.67

Total (Inclusive of GST) **19,390.67**

Printed on 25/1/2023 5:10:11 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.