



# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

HOCK CHUAN HENG CAR RENTAL &  
TRADING PTE LTD  
NO. 4 PETAIN ROAD, PETAIN COURT  
SINGAPORE 208086

TP China  
Xiao Chan.

Contact : 97479535, 62981936 91122549

## TAX INVOICE

Repair Code : CLM17587

Date in : 25/01/2023

Vehicle Num. : SMS3486H

Model : TOYOTA COROLLA ALTIS ELEGANCE (AUTO)(2WD)

Chassis/Eng# : MR2BE3BE100008086/1ZR0F21532

### Parts and Labour Assesment

| Description of part                                   | Qty | Unit Price | Amount          |
|-------------------------------------------------------|-----|------------|-----------------|
| REAR BOOTLID <i>Distorted</i>                         | 1   | 905.20     | ✓ 905.20        |
| REAR BOOTLID 'ALTIS' EMBLEM                           | 1   | 48.30      | ✓ 48.30         |
| REAR BOOTLID 'COROLLA' EMBLEM                         | 1   | 48.30      | ✓ 48.30         |
| REAR BOOTLID 'LOGO' EMBLEM                            | 1   | 66.20      | ✓ 66.20         |
| REAR BOOTLID HINGES L/R <i>Best</i>                   | 2   | 75.30      | ✓ 150.60        |
| REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i>      | 2   | 18.90      | + 37.80         |
| REAR BOOTLID INNER TRIM BOARD <i>new</i>              | 1   | 83.50      | + 83.50         |
| REAR BOOTLID LOCK STRIKER <i>new</i>                  | 1   | 16.20      | + 16.20         |
| REAR BOOTLID MECHANISM LOCK <i>2nd</i>                | 1   | 423.90     | 256 ✓ 423.90    |
| REAR BOOTLID NUMBER PLATE LAMP L/R <i>new</i>         | 2   | 69.70      | + 139.40        |
| REAR BOOTLID OUTER CHROME MOULDING <i>could</i>       | 1   | 209.50     | ✓ 209.50        |
| REAR BOOTLID OUTER CHROME MOULDING GARNISH <i>new</i> | 1   | 274.70     | + 274.70        |
| REAR BOOTLID REFLECTOR L/R <i>could</i>               | 2   | 775.70     | 1338 ✓ 1,551.40 |
| REAR BOOTLID WEATHER STRIP <i>lt</i>                  | 1   | 219.20     | ✓ 219.20        |
| REAR BUMPER <i>Distorted</i>                          | 1   | 563.00     | ✓ 563.00        |
| REAR BUMPER REFLECTOR L/R <i>could</i>                | 2   | 41.40      | ✓ 82.80         |
| REAR BUMPER REINFORCEMENT <i>Dented</i>               | 1   | 353.10     | ✓ 353.10        |
| REAR BUMPER REVERSE SENSOR <i>Dmg</i>                 | 2   | 298.90     | ✓ 597.80        |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

HOCK CHUAN HENG CAR RENTAL &  
TRADING PTE LTD  
NO. 4 PETAIN ROAD, PETAIN COURT  
SINGAPORE 208086

Contact : 97479535, 62981936 91122549

## TAX INVOICE

Repair Code : CLM17587

Date in : 25/01/2023

Vehicle Num. : SMS3486H

Model : TOYOTA COROLLA ALTIS ELEGANCE (AUTO)(2WD)

Chassis/Eng# : MR2BE3BE100008086/1ZR0F21532

|                                                |   |         |        |          |
|------------------------------------------------|---|---------|--------|----------|
| REAR BUMPER REVERSE SENSOR HOLDER <i>Nu</i>    | 2 | 39.60   | ✓      | 79.20    |
| REAR BUMPER SIDE RETAINER L/R <i>Nu</i>        | 2 | 106.70  | ✓      | 213.40   |
| REAR BUMPER TOW HOOK COVER <i>Del</i>          | 1 | 27.20   | ✓      | 27.20    |
| REAR END PANEL <i>Distorted</i>                | 1 | 653.20  | ✓      | 653.20   |
| REAR END PANEL ANTENNA SENSOR <i>amLd</i>      | 1 | 76.30   | ✓      | 76.30    |
| REAR END PANEL INNER TOP GARNISH <i>Del</i>    | 1 | 286.60  | ✓      | 286.60   |
| REAR EXHAUST HEAT COVER <i>Nu</i>              | 1 | 192.10  | +      | 192.10   |
| REAR EXHAUST RUBBER MOUNTING <i>3 Nu</i>       | 2 | 52.20   | +      | 104.40   |
| REAR EXHAUST SILENCER BOX                      | 1 | 1268.40 | +      | 1,268.40 |
| REAR FENDER INNER TRIM BOARD L/R <i>RH ton</i> | 2 | 393.20  | 393.20 | 786.40   |
| REAR FLOOR PANEL TOP BOARD COVER <i>Del</i>    | 1 | 987.70  | 357    | 987.70   |
| REAR FLOOR PANEL UNDER COVER <i>Del</i>        | 1 | 471.60  | 395    | 471.60   |
| REAR RH FENDER <i>Brckend.</i>                 | 1 | 1093.60 | ✓      | 1,093.60 |
| REAR TAILLAMP INNER PANEL L/R <i>Brckend.</i>  | 2 | 86.00   | ✓      | 172.00   |
| REAR TAILLAMP L/R <i>amLd</i>                  | 2 | 1297.70 | ✓      | 2,595.40 |
| REAR TAILLAMP LOWER BRACKET L/R <i>amLd</i>    | 2 | 69.20   | ✓      | 138.40   |
| REAR TAILLAMP SIDE COVER L/R <i>lt</i>         | 2 | 37.00   | ✓      | 74.00    |

11175.10

8381.32

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

HOCK CHUAN HENG CAR RENTAL &  
TRADING PTE LTD  
NO. 4 PETAIN ROAD, PETAIN COURT  
SINGAPORE 208086

Contact : 97479535, 62981936 91122549

## TAX INVOICE

Repair Code : CLM17587  
Date in : 25/01/2023  
Vehicle Num. : SMS3486H  
Model : TOYOTA COROLLA ALTIS ELEGANCE (AUTO)(2WD)  
Chassis/Eng# : MR2BE3BE100008086/1ZR0F21532

|                                              |              |                          |                            |
|----------------------------------------------|--------------|--------------------------|----------------------------|
|                                              |              | Subtotal before discount | 14,990.80                  |
| Percentage discount                          | 25%          |                          | 3,747.70                   |
|                                              |              | <b>Sub-total 1</b>       | <b>11,243.10</b>           |
| REAR BOOTLID CAMERA                          | <i>Detd</i>  | 1                        | 900.00 <i>480. 900.00</i>  |
| REAR BOOTLID INNER TRIM BOARD CLIPS - SET    | <i>men</i>   | 1                        | 50.00 <i>x 50.00</i>       |
| REAR BOOTLID NUMBER PLATE                    | <i>Detd</i>  | 1                        | 25.00 <i>- 25.00</i>       |
| REAR BOOTLID NUMBER PLATE HOLDER             | <i>Detd</i>  | 1                        | 50.00 <i>30. 50.00</i>     |
| REAR BUMPER CLIPS - SET                      | <i>men</i>   | 1                        | 80.00 <i>30 80.00</i>      |
| REAR END PANEL INNER TOP GARNISH CLIPS - SET | <i>men</i>   | 1                        | 40.00 <i>20 40.00</i>      |
| REAR FENDER INNER TRIM BOARD CLIPS L/R - SET | <i>men</i>   | 2                        | 50.00 <i>715 30 100.00</i> |
| REAR TAILLAMP CLIPS L/R - SET                | <i>men</i>   | 2                        | 25.00 <i>20 50.00</i>      |
| REAR WINDSCREEN SEAL                         | <i>3 men</i> | 1                        | 80.00 <i>40 80.00</i>      |
| REAR WINDSCREEN SEALANT                      |              | 1                        | 80.00 <i>40 80.00</i>      |
|                                              |              | Subtotal before discount | 1,455.00                   |
| Percentage discount                          | 0%           |                          | 0.00                       |
|                                              |              | <b>Sub-total 2</b>       | <b>1,455.00</b>            |
|                                              |              | <b>Parts-total</b>       | <b>12,698.10</b>           |

## LABOUR

To reset system after repair works *x* 500.00  
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor. *✓* 80.00

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

HOCK CHUAN HENG CAR RENTAL &  
TRADING PTE LTD  
NO. 4 PETAIN ROAD, PETAIN COURT  
SINGAPORE 208086

Contact : 97479535, 62981936 91122549

## TAX INVOICE

Repair Code : CLM17587

Date in : 25/01/2023

Vehicle Num. : SMS3486H

Model : TOYOTA COROLLA ALTIS ELEGANCE (AUTO)(2WD)

Chassis/Eng# : MR2BE3BE100008086/1ZR0F21532

to remove, reinstall windscreen (REAR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear bootlid mechanism lock outer handle reflector

120 150.00

80 120.00

1200 1,400.00

1300 1,600.00

100 120.00

80 80.00

3160

Labour Total

4,050.00

Parts & Labour Total

16,748.10

Adrian Lij  
01/02/23

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 4

09 Days

total: 12236.32

h/s : 9.8K

9.8K

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed

Witnessed by Repairer

Signature

Date: