

CS/CTI23000945/Tvp3

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**27 JAN 2023**

Estimate No. : b1 64805
Date Estimated : 27/01/2023
Prepared By : Foong Shih Jye

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Tan Beng Sim Vincent
55 Meyer Road
#21-05

Singapore 437978

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCX7000S	WBA5F32050FJ04531	26/06/2020	320i Sedan	24805

DESCRIPTION

To replace bumper front panel and front left side panel

✓ 1700 2,550.00

To spray paint bumper front panel and front left side panel

✓ 1826 1,923.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No financial modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

✓ 168 177.00

To carry out body cavity preservation.
(Per panel).

✓ 112 118.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

✓ 168 177.00

Sundries.

80? 150.00

Acknowledged by Repairer

Signature:

Date:

Total Labour 1: 5,095.00

DESCRIPTION

FRT LH SIDE PANEL

QTY

PRIC

VALUE

LH RETAINING FRAME

1

852.70

56 852.70

FRT BUMPER PANEL PRIMED (LINE PDC/P

1

87.60

nnx dis 87.60

1,118.55

de 1,118.55

7166.05

Total Parts : 2,058.85



Tan Jie 97495749/62563561
WP 20/2/23c WLO an
Resurvey before paint
tan jie e/haarts.com

Labour 1 : 5,095.00
Parts : 2,058.85
Labour 2 : 0.00
Excess : 0.00
Total GST @ 8% : 572.31
Grand Total : 7,726.16

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE**

Performance Motors

BMW Dealer



Final Report

Estimate No. : b1 64805
Date Estimated : 27/01/2023
Prepared By : Foong Shiuh Jye

Page No. :

- ESTIMATE REPAIR FOR -

Tan Beng Sim Vincent
55 Meyer Road
#21-05

Singapore 437978

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SCX7000S	WBA5F32050FJ04531	26/06/2020	320i Sedan	24805

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, front LH fenders include carrying out necessary repairs caused by the accident	1,700.00	0.00	1,700.00
To spray paint front bumper and front LH fender	1,826.00	0.00	1,826.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function	168.00	0.00	168.00
To carry out body cavity preservation (Per panel)	112.00	0.00	112.00
To check electrical wiring system at the front section for proper function	168.00	0.00	168.00
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH SIDE PANEL	852.70	1.00	0.00	852.70
FRT BUMPER PANEL PRIMED (LINE PDC/PMA)	1,118.55	1.00	0.00	1,118.55
# ADJUSTABLE BLIND RIVET	3.05	4.00	0.00	12.20

CA)
NEL ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,054.00
Total Parts :	1,983.45
Total Labour & Parts (before GST) :	6,037.45
Deduction for Excess :	
Total Repair Costs less Excess:	6,037.45
GST @8%:	483.00
Grand Total :	6,520.45

Performance Motors Limited.
Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

A Sime Darby Motors Company