



Final Report

Estimate No. : **b1 64805**
Date Estimated : **27/01/2023**
Prepared By : **Foong Shiuh Jye**

Page No. :

- ESTIMATE REPAIR FOR -

Tan Beng Sim Vincent
55 Meyer Road
#21-05

Singapore 437978

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SCX7000S	WBA5F32050FJ04531	26/06/2020	320i Sedan	24805

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, front LH fenders include carrying out necessary repairs caused by the accident	1,700.00	0.00	1,700.00
To spray paint front bumper and front LH fender	1,826.00	0.00	1,826.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function	168.00	0.00	168.00
To carry out body cavity preservation (Per panel)	112.00	0.00	112.00
To check electrical wiring system at the front section for proper function	168.00	0.00	168.00
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH SIDE PANEL	852.70	1.00	0.00	852.70
FRT BUMPER PANEL PRIMED (LINE PDC/PMA)	1,118.55	1.00	0.00	1,118.55
# ADJUSTABLE BLIND RIVET	3.05	4.00	0.00	12.20

SUPPLEMENTARY ITEMS

Total Labour :	4,054.00
Total Parts :	1,983.45
Total Labour & Parts (before GST) :	6,037.45
Deduction for Excess :	
Total Repair Costs less Excess:	6,037.45
GST @8%:	483.00
Grand Total :	6,520.45

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

