

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : YQ 5789P
Made : Toyota
Model : Dyna 150 SMT
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Front Bumper	1	\$ 468.20	\$ <i>de</i> 468.20	✓
2	Front Bumper Reinforcement	1	\$ 279.80	\$ <i>Rm</i> 279.80	✓
3	Front Bumper Bracket RH	1	\$ 232.70	\$ <i>X un</i> 232.70	
4	Front Bumper Bracket LH	1	\$ 232.70	\$ <i>Rm</i> 232.70	
5	Front Bumper Foglamp Garnish RH	1	\$ 105.30	\$ <i>X un</i> 105.30	
6	Front Bumper Foglamp Garnish LH	1	\$ 105.30	\$ <i>Rm</i> 105.30	
7	Front Grille Assembly	1	\$ 465.60	\$ <i>cur</i> 465.60	✓
8	Front Grille Emblem	1	\$ 78.40	\$ <i>ner</i> 78.40	✓
9	Front Panel	1	\$ 1,150.00	\$ <i>bt</i> 1,150.00	✓
10	Front Panel Emblem	1	\$ 67.20	\$ <i>ner</i> 67.20	✓
11	Front Wiper Panel	1	\$ 285.20	\$ <i>bt</i> 285.20	✓
12	Front Windscreen Glass Moulding	1	\$ 309.80	\$ <i>ner</i> 309.80	150 ✓
13	Front Headlamp Assembly RH	1	\$ 1,009.70	\$ <i>cur</i> 1,009.70	✓
14	Front Headlamp Assembly LH	1	\$ 1,009.70	\$ <i>cur</i> 1,009.70	✓
15	Front Headlamp Assembly Lower Rubber RH	1	\$ 38.10	\$ <i>X un</i> 38.10	
16	Front Headlamp Assembly Lower Rubber LH	1	\$ 38.10	\$ <i>de</i> 38.10	✓
17	Front Corner Panel RH	1	\$ 343.20	\$ <i>X un</i> 343.20	
18	Front Corner Panel LH	1	\$ 343.20	\$ <i>cur</i> 343.20	✓
19	Front Corner Garnish (Upper) RH	1	\$ 110.70	\$ <i>X un</i> 110.70	
20	Front Corner Garnish (Upper) LH	1	\$ 110.70	\$ <i>cur</i> 110.70	✓
21	Cabin Hinge (Front)	1	\$ 205.20	\$ <i>X un</i> 205.20	
22	Front Pillar Support Bar	1	\$ 455.30	\$ <i>X un</i> 455.30	
23	Aircon Pipe	1	\$ 289.70	\$ <i>Rm</i> 289.70	
24	Aircon Blower Motor	1	\$ 1,572.50	\$ <i>Rm</i> 1,572.50	350 ✓
25	Aircon Cooling Coil & Heater Assembly	1	\$ 1,882.20	\$ <i>Rm</i> 1,882.20	1500 ✓
26	Aircon Condenser Assembly	1	\$ 828.60	\$ <i>bt</i> 828.60	✓
27	Wiper Washer Tank	1	\$ 155.70	\$ <i>X un</i> 155.70	
28	Brake Pipe	1	\$ 135.80	\$ <i>X un</i> 135.80	
29	Front Wire Harness	1	\$ 428.70	\$ <i>X un</i> 428.70	
30	Side Mirror with Stand LH	1	\$ 690.30	\$ <i>Rm</i> 690.30	
31	Side Mirror Round LH	1	\$ 139.60	\$ <i>out</i> 139.60	✓
32	Front Dashboard Assembly	1	\$ 1,008.00	\$ <i>X un</i> 1,008.00	

33	Front Dashboard Reinforcement Bar	1	\$	794.30	\$ x 7	794.30	
34	Front Wiper Arm RH	1	\$	122.00	\$ x	122.00	
35	Front Wiper Arm LH	1	\$	122.00	\$ x	122.00	
36	Front Wiper Blade RH	1	\$	56.00	\$ x	56.00	
37	Front Wiper Blade LH	1	\$	56.00	\$ x	56.00	
38	Front Wiper Linkage	1	\$	420.00	\$ bt	420.00	✓
39	Front Wiper Motor	1	\$	760.00	\$ un 760 X	760.00	
40	Front Door LH	1	\$	1,600.00	\$ bt	1,600.00	✓
41	Front Door Outer Moulding LH	1	\$	188.20	\$ x un	188.20	
42	Front Door Upper Hinge LH	1	\$	89.95	\$ R 7	89.95	
43	Front Door Lower Hinge LH	1	\$	89.95	\$ R	89.95	
44	Front Door Checker LH	1	\$	149.70	\$ R	149.70	
45	Front Door Weatherstrip LH	1	\$	206.50	\$ R	206.50	
46	Front Door Arch Rubber LH	1	\$	75.60	\$ X	75.60	
47	Front Door Glass Channel LH	1	\$	185.70	\$ R	185.70	
48	Front Door Inner Lock LH	1	\$	305.70	\$ bt	305.70	✓
49	Front Door Lock Catch LH	1	\$	36.70	\$ X un	36.70	
50	Front Door Inner Trim Board LH	1	\$	672.30	\$ ana	672.30	✓
51	Front Door Glass LH	1	\$	721.10	\$ X un	721.10	
52	Front Door Power Window Motor LH	1	\$	586.30	\$ X un	586.30	
53	Front Door Regulator LH	1	\$	341.70	\$ bt	341.70	✓
54	Front Door Speaker LH	1	\$	245.10	\$ X un	245.10	
55	Front Door Pillar (Inner) LH	1	\$	387.40	\$ R R 7	387.40	
56	Front Floor Panel Side Garnish LH	1	\$	388.60	\$ R	388.60	
57	Front Door Pillar (Outer) LH	1	\$	398.60	\$ X	398.60	
58	Front Wheel Arch Panel LH	1	\$	192.10	\$ R	192.10	
59	Front Wheel Arch Rubber LH	1	\$	85.60	\$ R	85.60	
60	Front Step Panel Garnish LH	1	\$	281.70	\$ ana	281.70	✓
61	Rear Tailgate	1	\$	1,680.20	\$ bt	1,680.20	1500
62	Rear Tailgate "Dyna" Sticker	1	\$	57.60	\$ ana	57.60	✓
63	Rear Tailgate Hinge	2	\$	124.20	\$ bt	496.80	48.40 ✓
64	Rear Tailgate Side Lock RH	1	\$	192.60	\$ x R	192.60	
65	Rear Tailgate Side Lock LH	1	\$	192.60	\$ x R	192.60	
66	Rear Tailgate Stopper Bracket RH	1	\$	109.90	\$ bt	109.90	✓
67	Rear Tailgate Stopper Rubber RH	1	\$	48.60	\$ ana	48.60	✓
68	Rear Tailgate Stopper Bracket LH	1	\$	109.90	\$ x un	109.90	
69	Rear Tailgate Stopper Rubber LH	1	\$	48.60	\$ x un	48.60	
70	Rear Tailgate Lower Panel (End Panel)	1	\$	698.10	\$ bt	698.10	✓
71	Rear Taillamp Assembly RH	1	\$	345.80	\$ ana	345.80	✓
72	Rear Taillamp Panel RH	1	\$	255.60	\$ bt	255.60	✓
73	Rear Taillamp Assembly LH	1	\$	345.80	\$ ana	345.80	✓
74	Rear Taillamp Panel LH	1	\$	255.60	\$ R 7	255.60	
75	Rear Number Plate Bracket	1	\$	119.50	\$ bt	119.50	✓
76	Rear Number Plate Lamp	1	\$	139.20	\$ mi 5	139.20	✓
77	Spare Tyre Carrier	1	\$	385.90	\$ x un	385.90	

78	Spare Tyre Carrier Bracket	1	\$	185.20	\$ X	185.20	
79	Rear Exhaust Pipe	1	\$	895.00	\$ 67	895.00	✓
80	Rear Exhaust Pipe Mounting	1	\$	138.00	\$ X	138.00	
81	Rear Mudguard RH	1	\$	343.00	\$ X	343.00	
82	Rear Mudflap RH	1	\$	114.20	\$ X	114.20	
83	Rear Mudguard LH	1	\$	343.00	\$ X	343.00	
84	Rear Mudflap LH	1	\$	114.20	\$ X	114.20	
85	Rear Chassis Crossmember	1	\$	894.50	\$ 67 X	894.50	
86	Rear Side Gate RH	1	\$	1850 1,945.20	\$ 66	1,945.20	1800 ✓
87	Rear Side Gate LH	1	\$	1850 1,945.20	\$ 66	1,945.20	1800 ✓
88	Rear Side Gate Lower Panel RH	1	\$	845.20	\$ X 44	845.20	
89	Rear Side Gate Lower Panel LH	1	\$	845.20	\$ X 44	845.20	
			21,258.90		Parts Sub Total :		\$ 38,224.20
			-25%		25% Discount :		\$ 9,556.05
			15,944.17		PARTS TOTAL :		\$ 28,668.15

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	1	\$ 40.00	\$ 30 67 40.00
2	Front Grille Assembly Clips - Set	1	\$ 50.00	\$ 20 ne 50.00
3	Front Corner Panel Clips - Set	1	\$ 30.00	\$ 10 ne 30.00
4	Front Door Inner Trim Board LH Clips - Set	1	\$ 50.00	\$ 20 ne 50.00
5	Front Windscreen Glass Sealant	1	\$ 150.00	\$ ne 80 150.00
6	Front Panel Sealant	1	\$ 150.00	\$ 40 ne 150.00
7	Front Wiper Panel Sealant	1	\$ 120.00	\$ 30 ne 120.00
8	Front Windscreen Panel Sealant	1	\$ 200.00	\$ 60 ne 200.00
9	Front Door LH Sealant	1	\$ 150.00	\$ X ne 150.00
10	Front Panel Artwork Sticker	1	\$ 650.00	\$ 250 ne 650.00
11	Front Windscreen Panel Artwork Sticker	1	\$ 500.00	\$ 150 ne 500.00
12	Front Door LH Artwork Sticker	1	\$ 750.00	\$ 200 ne 750.00
13	Rear Number Plate	1	\$ 50.00	\$ 30 67 50.00
14	Rear Reverse Sensor	1	\$ 250.00	\$ 200 ne 250.00
15	Rear Reverse Camera	1	\$ 500.00	\$ X ne 500.00
16	Rear Tailgate "60km/h" Sticker	1	\$ 50.00	\$ ne 30 50.00
17	Rear Tailgate "13 Pax" Sticker	1	\$ 50.00	\$ ne 30 50.00
18	Rear Tailgate Artwork Sticker	1	\$ 1,000.00	\$ 200 ne 1,000.00
19	Rear Sidegate Top Stainless Steel Railing RH	1	\$ 1,500.00	\$ X ne 1,500.00
20	Rear Sidegate Top Stainless Steel Railing LH	1	\$ 1,500.00	\$ X ne 1,500.00
21	Rear Floor Panel Aluminium Plate	1	\$ 3,500.00	\$ X ne 3,500.00
22	Rear Tailgate Aluminium Plate	1	\$ 1,200.00	\$ 300 67 1,200.00
23	Rear Sidegate Aluminium Plate RH	1	\$ 1,800.00	\$ X ne 1,800.00
24	Rear Sidegate Aluminium Plate LH	1	\$ 1,800.00	\$ X ne 1,800.00
25	Rear Canopy	1	\$ 3,000.00	\$ X ne 3,000.00
26	Rear Reinforcement Beam	1	\$ 1,500.00	\$ 67 600 1,500.00
27	Rear Tailgate Lower Panel (End Panel) Sealant	1	\$ 150.00	\$ 50 ne 150.00
28	Rear Sidegate Sealant RH	1	\$ 150.00	\$ X ne 150.00

29	Rear Sidegate Sealant LH	1	\$	150.00	\$ K n n 150.00
30	Rear Tailgate Sealant	1	\$	150.00	\$ K n n 150.00
SPECIAL NETT TOTAL :					\$ 21,140.00

2230

Nos.	LABOUR	TOTAL S\$	
1	To Panel Beat, Remove & Refix Parts (Front)	\$ 700	1,500.00
2	To Spray Paint Affected Areas (Front)	\$ 1000	1,400.00
3	To Panel Beat, Remove & Refix Parts (Rear)	850 \$ 800	1,800.00
4	To Spray Paint Affected Areas (Rear)	1000 \$ 800	1,600.00
5	Wiring & Bulb Check (Front)	\$ 30	120.00
6	Wiring & Bulb Check (Rear)	\$ 30	100.00
7	To Remove & Refix Front Windscreen Glass	\$ 120	150.00
8	To Remove & Refix Aircon Cooling Coil & Heater Assembly	\$ 200 ✓	350.00
9	To Remove & Refix Aircon Blower Motor	\$ 100 ✓	300.00
10	To Remove & Refix Aircon Condenser & Top Up Gas	\$ 100 ✓	150.00
11	To Remove & Refix Front Dashboard Assembly	n \$ 180	500.00
12	To Transfer Front Door Mechanisms	\$ 60	150.00
13	To Remove & Refix Rear Reverse Sensor	\$ 30	150.00
14	To Remove & Refix Rear Camera	\$ X n n	150.00
15	To Remove & Refix Rear Exhaust Pipe	\$ 60	150.00
16	To Remove & Refix Rear Aluminium Plates	\$ 100 30	300.00
17	To Remove & Refix Rear Floor Panel Aluminium Plate	\$ n 250	400.00
18	To Remove & Refix Rear Canopy	\$ X n n	400.00
19	To apply anti rust on affected parts	\$ 50	400.00
20	To Conduct Water Leak Test	\$ X n n	100.00
21	To Send for Diagnostic and Reset Control Unit Programming & Calibration	\$ X n n	480.00
LABOUR TOTAL :		\$	10,650.00

4360

Tanjilini 97495749
 WP, 1/2/23 & 10/15
 L/S Resurvey after repair
 Tanjilini e/khanto.com
 12 days

- To check consistency of accident
- To check part prices

PARTS TOTAL : \$ 28,668.15
 SPECIAL NETT TOTAL : \$ 21,140.00
 LABOUR TOTAL : \$ 10,650.00
 GRAND TOTAL : \$ 60,458.15

22,534.17

L/S - 18,027.33
 = 18,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: