

ASS. REC. BY: Tajir

REF:

63/CT/23000 949/TVP3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 91000

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YQ5789P Yr Regn: 2022 / JanType: M.Car / M.Cycle / Bus / Van / Motor / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna c.c 2754Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 45843 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHH4GV4600K00/680Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 / R15R: 145 / 80R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at RifstDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6/6 mmL/Bal. 6/6 mmD.O.I. 01/02/23

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.L. (\$ _____)

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **YQ 5789P**

Made : Toyota

Model : Dyna 150 5MT

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 468.20	\$ <i>de</i> 468.20
2	Front Bumper Reinforcement	1	\$ 279.80	\$ <i>Rm</i> 279.80
3	Front Bumper Bracket RH	1	\$ 232.70	\$ <i>Xm</i> 232.70
4	Front Bumper Bracket LH	1	\$ 232.70	\$ <i>Rm</i> 232.70
5	Front Bumper Foglamp Garnish RH	1	\$ 105.30	\$ <i>Xm</i> 105.30
6	Front Bumper Foglamp Garnish LH	1	\$ 105.30	\$ <i>Rm</i> 105.30
7	Front Grille Assembly	1	\$ 465.60	\$ <i>cur</i> 465.60
8	Front Grille Emblem	1	\$ 78.40	\$ <i>ner</i> 78.40
9	Front Panel	1	\$ 1,150.00	\$ <i>bt</i> 1,150.00
10	Front Panel Emblem	1	\$ 67.20	\$ <i>ner</i> 67.20
11	Front Wiper Panel	1	\$ 285.20	\$ <i>bt</i> 285.20
12	Front Windscreen Glass Moulding	1	\$ 309.80	\$ <i>ner</i> 309.80
13	Front Headlamp Assembly RH	1	\$ 1,009.70	\$ <i>cur</i> 1,009.70
14	Front Headlamp Assembly LH	1	\$ 1,009.70	\$ <i>cur</i> 1,009.70
15	Front Headlamp Assembly Lower Rubber RH	1	\$ 38.10	\$ <i>Xm</i> 38.10
16	Front Headlamp Assembly Lower Rubber LH	1	\$ 38.10	\$ <i>de</i> 38.10
17	Front Corner Panel RH	1	\$ 343.20	\$ <i>Xm</i> 343.20
18	Front Corner Panel LH	1	\$ 343.20	\$ <i>cur</i> 343.20
19	Front Corner Garnish (Upper) RH	1	\$ 110.70	\$ <i>Xm</i> 110.70
20	Front Corner Garnish (Upper) LH	1	\$ 110.70	\$ <i>cur</i> 110.70
21	Cabin Hinge (Front)	1	\$ 205.20	\$ <i>Xm</i> 205.20
22	Front Pillar Support Bar	1	\$ 455.30	\$ <i>Xm</i> 455.30
23	Aircon Pipe	1	\$ 289.70	\$ <i>Rm</i> 289.70
24	Aircon Blower Motor	1	\$ 1,572.50	\$ <i>Rm</i> 1,572.50
25	Aircon Cooling Coil & Heater Assembly	1	\$ 1,882.20	\$ <i>Rm</i> 1,882.20
26	Aircon Condenser Assembly	1	\$ 828.60	\$ <i>bt</i> 828.60
27	Wiper Washer Tank	1	\$ 155.70	\$ <i>Xm</i> 155.70
28	Brake Pipe	1	\$ 135.80	\$ <i>Xm</i> 135.80
29	Front Wire Harness	1	\$ 428.70	\$ <i>Xm</i> 428.70
30	Side Mirror with Stand LH	1	\$ 690.30	\$ <i>Rm</i> 690.30
31	Side Mirror Round LH	1	\$ 139.60	\$ <i>cur</i> 139.60
32	Front Dashboard Assembly	1	\$ 1,008.00	\$ <i>Xm</i> 1,008.00

33	Front Dashboard Reinforcement Bar	1	\$	794.30	\$ x }	794.30
34	Front Wiper Arm RH	1	\$	122.00	\$ x }	122.00
35	Front Wiper Arm LH	1	\$	122.00	\$ x }	122.00
36	Front Wiper Blade RH	1	\$	56.00	\$ x }	56.00
37	Front Wiper Blade LH	1	\$	56.00	\$ x }	56.00
38	Front Wiper Linkage	1	\$	420.00	\$ Bt ✓	420.00
39	Front Wiper Motor	1	\$	760.00	\$ w n X	760.00
40	Front Door LH	1	\$	1,600.00	\$ bt -	1,600.00
41	Front Door Outer Moulding LH	1	\$	188.20	\$ x w n	188.20
42	Front Door Upper Hinge LH	1	\$	89.95	\$ x }	89.95
43	Front Door Lower Hinge LH	1	\$	89.95	\$ x }	89.95
44	Front Door Checker LH	1	\$	149.70	\$ x }	149.70
45	Front Door Weatherstrip LH	1	\$	206.50	\$ x }	206.50
46	Front Door Arch Rubber LH	1	\$	75.60	\$ x }	75.60
47	Front Door Glass Channel LH	1	\$	185.70	\$ x }	185.70
48	Front Door Inner Lock LH	1	\$	305.70	\$ Bt ✓	305.70
49	Front Door Lock Catch LH	1	\$	36.70	\$ x w n	36.70
50	Front Door Inner Trim Board LH	1	\$	672.30	\$ Cua ✓	672.30
51	Front Door Glass LH	1	\$	721.10	\$ x w n	721.10
52	Front Door Power Window Motor LH	1	\$	586.30	\$ x w n	586.30
53	Front Door Regulator LH	1	\$	341.70	\$ Bt ✓	341.70
54	Front Door Speaker LH	1	\$	245.10	\$ x w n	245.10
55	Front Door Pillar (Inner) LH	1	\$	387.40	\$ R R }	387.40
56	Front Floor Panel Side Garnish LH	1	\$	388.60	\$ x }	388.60
57	Front Door Pillar (Outer) LH	1	\$	398.60	\$ x }	398.60
58	Front Wheel Arch Panel LH	1	\$	192.10	\$ x }	192.10
59	Front Wheel Arch Rubber LH	1	\$	85.60	\$ x }	85.60
60	Front Step Panel Garnish LH	1	\$	281.70	\$ Cua	281.70
61	Rear Tailgate	1	\$	1,680.20	\$ bt -	1,680.20
62	Rear Tailgate "Dyna" Sticker	1	\$	57.60	\$ w n	57.60
63	Rear Tailgate Hinge	2x	\$	124.20	\$ bt -	496.80
64	Rear Tailgate Side Lock RH	1	\$	192.60	\$ x R	192.60
65	Rear Tailgate Side Lock LH	1	\$	192.60	\$ x R	192.60
66	Rear Tailgate Stopper Bracket RH	1	\$	109.90	\$ bt -	109.90
67	Rear Tailgate Stopper Rubber RH	1	\$	48.60	\$ Cua	48.60
68	Rear Tailgate Stopper Bracket LH	1	\$	109.90	\$ x w n	109.90
69	Rear Tailgate Stopper Rubber LH	1	\$	48.60	\$ x w n	48.60
70	Rear Tailgate Lower Panel (End Panel)	1	\$	698.10	\$ bt -	698.10
71	Rear Taillamp Assembly RH	1	\$	345.80	\$ Cua	345.80
72	Rear Taillamp Panel RH	1	\$	255.60	\$ bt -	255.60
73	Rear Taillamp Assembly LH	1	\$	345.80	\$ Cua	345.80
74	Rear Taillamp Panel LH	1	\$	255.60	\$ R y	255.60
75	Rear Number Plate Bracket	1	\$	119.50	\$ bt -	119.50
76	Rear Number Plate Lamp	1	\$	139.20	\$ m i s	139.20
77	Spare Tyre Carrier	1	\$	385.90	\$ x w n	385.90

78	Spare Tyre Carrier Bracket	1	\$	185.20	\$ X	185.20
79	Rear Exhaust Pipe	1	\$	895.00	\$ 67	895.00
80	Rear Exhaust Pipe Mounting	1	\$	138.00	\$ X	138.00
81	Rear Mudguard RH	1	\$	343.00	\$ X	343.00
82	Rear Mudflap RH	1	\$	114.20	\$ X	114.20
83	Rear Mudguard LH	1	\$	343.00	\$ X	343.00
84	Rear Mudflap LH	1	\$	114.20	\$ X	114.20
85	Rear Chassis Crossmember	1	\$	894.50	\$ 67 X	894.50
86	Rear Side Gate RH	1	\$	1,945.20	\$ 66	1,945.20
87	Rear Side Gate LH	1	\$	1,945.20	\$ 66	1,945.20
88	Rear Side Gate Lower Panel RH	1	\$	845.20	\$ X un	845.20
89	Rear Side Gate Lower Panel LH	1	\$	845.20	\$ 2 un	845.20
Parts Sub Total :					\$	38,224.20
25% Discount					\$	9,556.05
PARTS TOTAL :					\$	28,668.15

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	1	\$	40.00
2	Front Grille Assembly Clips - Set	1	\$	50.00
3	Front Corner Panel Clips - Set	1	\$	30.00
4	Front Door Inner Trim Board LH Clips - Set	1	\$	50.00
5	Front Windscreen Glass Sealant	1	\$	150.00
6	Front Panel Sealant	1	\$	150.00
7	Front Wiper Panel Sealant	1	\$	120.00
8	Front Windscreen Panel Sealant	1	\$	200.00
9	Front Door LH Sealant	1	\$	150.00
10	Front Panel Artwork Sticker	1	\$	650.00
11	Front Windscreen Panel Artwork Sticker	1	\$	500.00
12	Front Door LH Artwork Sticker	1	\$	750.00
13	Rear Number Plate	1	\$	50.00
14	Rear Reverse Sensor	1	\$	250.00
15	Rear Reverse Camera	1	\$	500.00
16	Rear Tailgate "60km/h" Sticker	1	\$	50.00
17	Rear Tailgate "13 Pax" Sticker	1	\$	50.00
18	Rear Tailgate Artwork Sticker	1	\$	1,000.00
19	Rear Sidegate Top Stainless Steel Railing RH	1	\$	1,500.00
20	Rear Sidegate Top Stainless Steel Railing LH	1	\$	1,500.00
21	Rear Floor Panel Aluminium Plate	1	\$	3,500.00
22	Rear Tailgate Aluminium Plate	1	\$	1,200.00
23	Rear Sidegate Aluminium Plate RH	1	\$	1,800.00
24	Rear Sidegate Aluminium Plate LH	1	\$	1,800.00
25	Rear Canopy	1	\$	3,000.00
26	Rear Reinforcement Beam	1	\$	1,500.00
27	Rear Tailgate Lower Panel (End Panel) Sealant	1	\$	150.00
28	Rear Sidegate Sealant RH	1	\$	150.00

29	Rear Sidegate Sealant LH	1	\$ 150.00	\$ X n n 150.00
30	Rear Tailgate Sealant	1	\$ 150.00	\$ X n n 150.00
SPECIAL NETT TOTAL :				\$ 21,140.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts (Front)	\$ 700 1,500.00
2	To Spray Paint Affected Areas (Front)	\$ 1000 1,400.00
3	To Panel Beat, Remove & Refix Parts (Rear)	\$ 800 1,800.00
4	To Spray Paint Affected Areas (Rear)	\$ 800 1,600.00
5	Wiring & Bulb Check (Front)	\$ 30 120.00
6	Wiring & Bulb Check (Rear)	\$ 30 100.00
7	To Remove & Refix Front Windscreen Glass	\$ 120 150.00
8	To Remove & Refix Aircon Cooling Coil & Heater Assembly	\$ 3200 ✓ 350.00
9	To Remove & Refix Aircon Blower Motor	\$ 3100 ✓ 300.00
10	To Remove & Refix Aircon Condenser & Top Up Gas	\$ 3100 ✓ 150.00
11	To Remove & Refix Front Dashboard Assembly	n n \$ 8180 500.00
12	To Transfer Front Door Mechanisms	\$ 60 150.00
13	To Remove & Refix Rear Reverse Sensor	\$ 30 150.00
14	To Remove & Refix Rear Camera	\$ X n n 150.00
15	To Remove & Refix Rear Exhaust Pipe	\$ 60 150.00
16	To Remove & Refix Rear Aluminium Plates	\$ 1600 30 300.00
17	To Remove & Refix Rear Floor Panel Aluminium Plate	\$ n n 750 400.00
18	To Remove & Refix Rear Canopy	\$ X n n 400.00
19	To apply anti rust on affected parts	\$ 50 400.00
20	To Conduct Water Leak Test	\$ X n n 100.00
21	To Send for Diagnostic and Reset Control Unit Programming & Calibration	\$ X n n 480.00
LABOUR TOTAL :		\$ 10,650.00

Tanfahin 97495749
 WP 1/2/23 & 2015
 L/S Resurvey after repair
 Tanfahin e/khanto.com
 12 days

- To check consistency of accident
- To check part prices

PARTS TOTAL : \$ 28,668.15
 SPECIAL NETT TOTAL : \$ 21,140.00
 LABOUR TOTAL : \$ 10,650.00
GRAND TOTAL : \$ 60,458.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: